# UTAH'S 1998 303(d) LIST OF WATERS

### I. METHODOLOGY FOR DEVELOPING THE 303(d) LIST

#### A. Streams:

1. Any receiving waterbody on which a facility is located that requires a Utah Pollution Discharge Elimination System discharge permit renewal between April 1, 1998 and March 31, 2000.

The parameters listed with UPDES discharge permit renewals in Table 1-c are effluent limited and are not violations of the State's water quality standards. Total Maximum Daily Load Analyses are calculated to determine the degree of treatment which must be performed before the effluent can be discharged in order to maintain beneficial use.

- 2. Any waterbody identified through Nonpoint Source Program (319) assessment procedures as having impairments to one or more of its beneficial uses.
- 3. Any stream assessed through the Stream Water Quality Assessment Program as partially supporting or not supporting one or more of its beneficial uses.

#### B. Lakes:

1. Any receiving waterbody on which a facility is located that requires a Utah Pollution Discharge Elimination System discharge permit renewal between April 1, 1998 and March 31, 2000.

The parameters listed with UPDES discharge permit renewals in Table 1-c are effluent limited and are not violations of the State's water quality standards. Total Maximum Daily Load Analyses are calculated to determine the degree of treatment which must be performed before the effluent can be discharged in order to maintain beneficial uses.

2. Any waterbody identified through the Lake Water Quality Assessment Program, the Clean Lakes Program (314) or the Nonpoint Source Program as partially supporting or not supporting one or more of its beneficial uses.

### C. Criteria for Listing Waterbodies on the 303(d) List.

As previously stated, Utah lists all waterbodies on the 303(d) list for which a UPDES discharge permit renewal is required during the current 303(d) cycle. Waterbodies with permit renewals between April 1, 1998 and March 31, 2000 were listed. Any waterbody assessed as 'partially supporting' or 'not supporting' its beneficial uses are listed with the exception of those waterbodies for which a Total Maximum Daily Load (TMDL) has been completed and approved by EPA.

Tables A-1 through A-4 are the criteria used for determining beneficial use support of waterbodies that are not listed because of a UPDES discharge permit renewal. For lakes and reservoirs the same criteria are used with the exception of the tables for conventional parameters; pH, dissolved oxygen and temperature; for 3A (cold water game fish), 3B (warm water game fish) and 3C (warm water non-game fish). Additional criteria

for determining beneficial use support for lakes and reservoirs are listed in the narrative in the last part of this section. The total phosphorus method for identifying waters as needing further study is not applied to lakes and reservoirs. The State of Utah exercises discretion in using data or information that goes beyond the criteria listed in the following tables and/or narrative for listing waterbodies and can include other types of information and best professional judgement.

| Table A-1. Criteria for Assessing Water as a Source of Drinking Water-Class 1C |  |  |  |  |  |  |
|--|--|--|--|--|--|--|
| Degree of Use<br>Support   | Field Monitoring<br>(Toxicants)  | Restrictions   |  |  |  |  |
| Full   | For any one pollutant, no more than one violation of criterion.  | No source water closures or advisories   |  |  |  |  |
| Partial  | For any one pollutant, two or more violations of the criterion, but violations occurred in $\leq 10\%$ of the samples.   | One or more drinking water source advisories lasting less than 30 days per year. |  |  |  |  |
| Non  | For any one pollutant, two or more violations of the criterion, and violations occurred in more than 10% of the samples. | One or more drinking water source advisories lasting greater than 30 days.       |  |  |  |  |

| Degree of Use<br>Support | Restrictions   | Fecal Coliform Bacteria  |
|--------------------------|--|--|
| Full                     | No bathing area closures or restrictions in effect during reporting period.  | Criterion 1 and Criterion 2 met.   |
| Partial                  | On average, one bathing area closure per year of less than one week's duration.  | Geometric mean met; not more than 25 percent of samples exceed 400 per 100 ml. |
| Non                      | On average, one bathing area closure per year of greater than one week's duration, or more than one bathing area closure per year. | Neither geometric mean nor maximum criteria limits achieved.                   |

**Criterion 1** = The geometric mean of the fecal coliform bacteria level should not exceed 200 per 100 mL for any 30-day period.

**Criterion 2** = Not more than 10 percent of the total samples taken during any 30 day period should have a density that exceeds 400 per 100 mL.

| Table A-3. Criteria for assessing Aquatic Life Beneficial Support-Classes 3A, 3B, 3C, 3D |  |  |  |  |  |  |
|--|--|--|--|--|--|--|
| Degree of Use Support  | Conventional Parameters (pH, DO, Temperature)  | Toxic Parameters (priority pollutants, chlorine, and ammonia)  |  |  |  |  |
| Full   | For any one pollutant, no more than one exceedance of criterion or criterion was not exceeded in < 10% of the samples if there were two or more exceedances. | For any one pollutant, no more than one violation of acute criteria.   |  |  |  |  |
| Partial  | For any one pollutant, criterion was exceeded two times, and criterion was exceeded in more than 10% but not more than 25% of the samples.                   | For any one pollutant, two or more violations of the acute criterion, but violations occurred in $\leq 10\%$ of the samples.   |  |  |  |  |
| Non  | For any one pollutant, criterion was exceeded two times, and criterion was exceeded in more than 25% of the samples.   | For any one pollutant, two or more violations of the acute criterion, and violations occurred in more than 10% of the samples. |  |  |  |  |

### **Total Phosphorus Assessment**

For total phosphorus, the following criteria were used to identify waters as 'needing further evaluation'.

If the **pollution indicator value** for total phosphorus (0.05 mg/L) was exceeded in more than 10% of the samples, and the mean of all samples was > 0.06 mg/L the waterbody was identified as 'needing further evaluation or study' before a decision to list a stream waterbody on the 303(d) list. Additional evaluations could include benthic macroinvertebrate data, diurnal dissolved oxygen data, habitat quality evaluations, and fisheries data. Reports published or information collected by other entities can be used to determine beneficial use support.

# Table A-4. Criteria for assessing Agricultural Beneficial Use - Class 4

| Degree of Use Support | Conventional Parameter<br>(Total Dissolved Solids)  | Toxic Parameters   |
|-----------------------|---|--|
| Full                  | Criterion exceeded in less than two samples and in $< 10\%$ of the samples if there were two or more exceedances.   | For any one pollutant, no more than one violation of criterion.  |
| Partial               | Criterion was exceeded two times, and criterion was exceeded in more than 10% but not more than 25% of the samples. | For any one pollutant, two or more violations of the criterion, but violations occurred in $\leq 10\%$ of the samples.   |
| Non                   | Criterion was exceeded two times, and criterion was exceeded in more than 25% of the samples.                       | For any one pollutant, two or more violations of the criterion, and violations occurred in more than 10% of the samples. |

## D. Additional Criteria for Listing Lakes and Reservoirs.

The criteria for listing lakes and reservoirs under Class 1C (source of drinking water), 2A (recreation), and Class 4 (agricultural use) are the same as listed in Tables A-1, A-2, and A-4. For determing beneficial use support for aquatic life use support 3A, 3B, and 3C the following proceedure was used.

An initial support status is determined for the conventional parameters (dissolved oxygen, temperature, and pH) according to the national 305(b) criteria. For any one pollutant or stressor, when the criteria is exceeded in less than or equal to 10 percent of the measurements a designation of fully supporting was assigned. When the criteria was exceeded in greater than 10, but less than 25 percent of the measurements, a designation of partially supporting was assigned. When the criteria was exceeded in greater than 25 percent of the measurements, a designation of non supporting was assigned. The criteria values utilized in our evaluations were: dissolved oxygen, 4.0 mg/L for Class 3A, and 3.0 mg/L for Classes 3B and 3C.; temperature, 20° C for Class 3A and 27° C for Class 3B and Class 3C.; pH, less than 6.5 or greater than 9.0 for all classes. The overall initial support status is based on an evaluation of all three of these parameters. If all of the parameters are fully supporting then the initial support status is fully supporting. All other combinations puts the waterbody into a partial supporting category.

Next there is a modification of the initial support status through an evaluation of the trophic state index (TSI), winter dissolved oxygen conditions with reported fish kills, and the presence of significant blue green algal species in the phytoplankton community. Although based to an extent on professional judgement, a shift downward of one status is made if two of the three criteria indicate there is an impairment in the water quality.

A final determination to list the waterbody is made through an evaluation of the historical beneficical use support. Because many of our reservoirs and lakes water quality are greatly influenced by annual water inputs, we feel it necessary to incorporate such an evaluation. In general, if a waterbody exhibits a beneficial use that is consistently partial supporting or not supporting, it should be listed on the 303(d) list. However, if a waterbody exhibits a mixture of partially and fully supporting conditions over a period of time we feel that it should not be listed at this time but continued to be evaluated.

### E. Criteria for Removing Waterbodies from the 303(d) List

- Waterbody was placed on list due to error in assessment or because waterbody was listed incorrectly in place of another waterbody or any other error not based on water quality assessment.
- 2. Most recent data assessment indicates that the waterbody is supporting all of its designated beneficial uses.
- 3. Total Maximum Daily Load Analysis has been completed and approved by EPA.
- 4. Existing waterbody delineation has changed.
  - a. The waterbody has been changed by dividing it into several waterbodies.
  - b. The waterbody boundaries have been changed and it is now a part of a different waterbody or portions of the waterbody are included in newly defined waterbodies.
- 5. Change in the method(s) of determining beneficial use support.

Methodology change would cause assessment to indicate that all beneficial uses are fully supported.

6. Change in state water quality standards or pollution indicator values.

A change in the standards or pollution indicators would change assessment to fully supporting all beneficial uses.

- A determination that insufficient amounts of data were collected to place the waterbody on the list
  originally, e.g., too few samples collected to make a reliable determination of
  beneficial use support.
- 8. Utah exercises discretion in using data or information that goes beyond the criteria listed above in determining whether to delist a waterbody and can include other types of information and best professional judgement.

### II. DATA AND INFORMATION USED TO PREPARE 303(D) LIST

The state of Utah relied upon the following sources of data and information to prepare its 303(d) list.

- A. Those waters listed in the 305(b) report as "partially meeting" or "not meeting" designated uses. Waters listed in the 305(b) report as not fully meeting designated beneficial uses, but have an EPA approved TMDL, were not listed on the 303(d) list. These designations were arrived at using chemical, physical and biological data collected by the state as well as data collected through cooperative agreements with the United States Forest Service, the United States Bureau of Land Management, United States Park Service, Salt Lake City, and the Central Utah Water Conservancy District.
- B. Dilution equations were used to develop waste load allocations for the UPDES discharge permit TMDLs to determine acceptable effluent discharge limits that would attain water quality standards

and protect the receiving water from having its beneficial uses impaired.

- C. Reports published by other government entities were used to determine beneficial use support. These included the Aquatic Resources Technical Report for the Central Utah Conservancy District's Upalco Unit Replacement Project and Uinta Replacement Project Report. As previously mentioned, cooperative monitoring programs with other governmental agencies were used to enhance the assessment capabilities of the State. In addition, technical advisory committees were established in several watersheds and they assisted in the assessment and reviewed reports that were prepared by the Division of Water Quality. These advisory committees include representatives from federal, state, county, and private groups. The Division received information from the Utah Division of Wildlife Resources on the fisheries in the Sevier River Basin. This information was not used to determine beneficial use support during this reporting cycle because it was not received in time to be included in the assessment. The information and data are being reviewed and the Division will determine how to use these data. It is included in the submittal as a comment on the list.
- D Nonpoint sources assessments which have identified impaired waters were used to list waters. These assessments were done by the State's nonpoint source committee and included information gathered by different agencies throughout the state including the National Resource Conservation Service. Nonpoint Source Project Implementation Plans were reviewed to identify problems and list impacts.

#### III. PRIORITIZATION OF TMDL WATERBODIES

The following criteria were used to prioritize TMDL Waters:

#### A. Severity of pollution and beneficial uses of waters.

UPDES permit renewal TMDLs received a high priority because many of the industrial permits required effluent limits on parameters that could be toxic to aquatic life as well as a danger to human health. In addition, the volume of the effluent discharged by the permittee can be a major component of the flow after the point of discharge. Severity of pollution is also used in determining the priority of nonpoint source TMDLs.

## B. Programmatic needs regarding UPDES permitting.

Utah's UPDES program is based upon a five-year permit renewal cycle. Permit renewals have been set up so that the number of permit renewals each year during the five year cycle are approximately equal. Because of this, the UPDES permit TMDLs are given a high priority so that the TMDL can be completed in time for the permit to be renewed because of the statutory requirements for permits to be issued.

# **C.** Basin Planning Cycles

The Division of Water Quality has currently divided the state into ten watershed management units. These units were combined to create five monitoring regions or units that are sampled intensively once every five years. This schedule allows the state to monitor a majority of the perennial streams state-wide to identify those waters that are not meeting beneficial uses. It is part of the Division's water quality management plan to complete some of the TMDLs in each of these watersheds during the five year cycle. This would allow the Division to develop a water quality management plan for each of the basins based upon the

results of the assessment and TMDLs in sub-watersheds.

### D. On-going Activities Within the Watershed

The Division uses water quality related projects and activities that are on-going in a watershed to prioritize its TMDL waterbodies. The Division has cooperated with the Natural Resources Conservation Service to implement TMDL work and water quality management plans throughout the state and will continue to do so. This cooperation provides additional funding and staff for water quality related assessments and improvements. The Division has and will continue to work with the Division of Water Resources to coordinate work when that Division produces its state water plans for each basin.

## E. Economic and social impact on communities, businesses, and citizens.

Economic and social impact on different sectors of the public are used to help prioritize TMDLs. The need to develop a TMDL to allocate discharges of water quality parameters to prevent the closure of industries or create undo burdens on communities and individuals is used in developing TMDL priorities.

### F. The degree of public interest, support, and resource importance.

This information is also used to assist in prioritizing TMDL waterbodies. Public interest has played a significant role in developing TMDLs in various watersheds. The lower Bear River is but one example where public interest as well as other parties was used as a ranking criteria to list waterbodies high on the list for TMDL completion. Most of those TMDLs were completed in the 1996-1998 reporting cycle.

#### IV. PROPOSED SCHEDULE FOR COMPLETION OF TMDLS

A TMDL is basically defined as the amount of a pollutant that must be removed from a waterbody in order that water quality standards may be achieved in those areas where the standards are exceeded or beneficial uses are impaired.

There are eight components of a TMDL that need to be addressed to receive EPA approval:

- A description of the water quality standards applicable for the area in question. This includes beneficial uses, narrative standards, numeric criteria and the antidegradation policy and procedure;
- 2. A quantifiable endpoint that a waterbody needs to achieve, e.g., total permitted lbs. per day of a certain parameter, or other appropriate endpoints such as temperature, etc.;
- 3. A quantified pollution reduction target. e.g., the total lbs. per day that needs to be reduced, or other appropriate indicators such as percent removal of pollutant;
- 4. All significant sources of the "stressor" must be identified or accounted for in some manner;

- 5. There must be an appropriate level of technical analysis;
- 6. The Clean Water Act Requires a margin of safety;
- 7. An apportion of responsibility for taking actions, e.g., who is causing what and how many lbs. per day of a pollutant is this land owner or entity responsible for, and lastly;
- 8. There must be some level of public involvement or review.

The Division has determined that there are approximately 467 TMDLs that will need to be addressed during the next twelve years. That breaks down to approximately 313 UPDES permits, 82 lakes and reservoirs and 72 river/stream segments for that time period. During the next two years, the following TMDLs are scheduled for completion:

## A. Municipal and Industrial Point Source Discharge Permit Renewals [UPDES Permits]: 50

# B. Lakes and Reservoirs (5)

East Canyon Reservoir - Weber River Drainage Mantua Reservoir - Bear Lake Drainage Pelican Lake - Green River Drainage Scofield Reservoir - Green River Drainage Ken's Lake [Moab] - Upper Colorado River Basin

## **B.** River and Stream Segments (9)

Jordan River (4 Segments) - Jordan River Drainage Upper Price River - Green River Drainage East Canyon Creek - Weber River Drainage Lower Uinta River I - Green River Drainage Dry Gulch Creek - Green River Drainage Little Bear River - Bear River Drainage

The remaining TMDLs are scheduled to be completed over the following ten years (2000-2010). Our plans call for approximately 16% of the total number of TMDLs being completed in the first four years, 48% during the next four years and the remaining 36% being completed by the end of the twelve years.

The number of TMDLs scheduled to be completed during the 12 years may vary from the above percentages somewhat because of manpower and resources available, change in federal regulations, identification of new TMDL waters, delisting of TMDL waters, and increased TMDLs related to UPDES permitting.

This effort will require coordination and cooperation with private land owners, the Bureau of Land Management and the Forest Service. Citizens advisory committees and technical advisory committees are being established for each area to further the effort. We anticipate that division staff will need to be increased.

# V. Utah's 1998 303(d) List Submittal to EPA

Table 1-a. Utah's 1998 303(d) List of Lake and Reservoir Waterbodies Identified as Needing Total

Maximum Daily Load Analyses (TMDLs).

Table 1-b. Utah's 1998 303(d) List of Stream and River Waterbodies Identified as Needing Total Maximum

Daily Load Analyses (TMDLs).

Table 1-c. Utah's 1998 303(d) List of Receiving Waters with Utah Pollution Discharge Elimination System

Discharge Permit Renewals Needing Total Maximum Daily Load Analyses (TMDLs).

Table 1-d. Utah's 1998 303(d) List of Utah Pollution Discharge Elimination System
Total Maximum Daily Load Analyses (TMDLs) Completed During the 19961998 Cycle. Completed TMDLs Will Be Removed When Approved by EPA.

Table 2-a. Lake and Reservoir Waterbodies to Be Removed from Utah's 1996 303(d) List of Water Quality Impaired Waters.

Table 2-b. River and Stream Waterbodies to Be Removed from Utah's 1996 303(d) List of Water Quality Impaired Waters.

Table 3. Status of Waterbodies Targeted for Total Maximum Daily Load Analyses During the 1996-1998 Reporting Cycle.

Table 1-a. Utah's 1998 303(d) List of Lake and Reservoir Waterbodies Identified as Needing Total Maximum Daily Load Analyses (TMDLs).

| Waterbody Name        | Waterbody<br>Size<br>(Acres) | Specific Pollutant or Stressor                                   | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments   |
|-----------------------|------------------------------|--|---|---|---|--|
| GREAT SALT LAKE BASIN |                              |  |   |   |   |  |
| UTAH LAKE DRAINAGE    |                              |  |   |   |   |  |
| Big East Lake         | 23                           | Total Phosphorus, Dissolved<br>Oxygen, Temperature               | Low   | No  |   |  |
| Deer Creek Reservoir  | 2,965                        | Total Phosphorus, Dissolved<br>Oxygen                            | Low   | No  |   |  |
| Mill Hollow Reservoir | 15                           | Total Phosphorus, Dissolved<br>Oxygen, pH                        | Low   | No  |   |  |
| Marshall Reservoir    | 98                           | Dissolved Oxygen   | Low   | No  |   |  |
| Utah Lake             | 96,900                       | Total Phosphorus, Total Dissolved<br>Solids, Trophic State Index | Low   | No  |   |  |
| GREAT SALT LAKE BASIN |                              |  |   |   |   |  |
| WEBER RIVER DRAINAGE  |                              |  |   |   |   |  |
| Causey Reservoir      | 142                          | Dissolved Oxygen   | Low   | No  |   |  |
| East Canyon Reservoir | 173                          | Total Phosphorus, Dissolved<br>Oxygen                            | High  | Yes   |   | TMDL may be completed depending on available data. |
| Echo Reservoir        | 1,394                        | Dissolved Oxygen, pH   | Low   | No  |   |  |
| Pineview Reservoir    | 2,874                        | Total Phosphorus, Dissolved<br>Oxygen, Temperature               | Low   | No  |   |  |
| Willard Bay Reservoir | 10,000                       | Total Phosphorus   | Low   | No  |   |  |
| GREAT SALT LAKE BASIN |                              |  |   |   |   |  |
| Rush Lake             | 80                           | Total Dissolved Solids, Total<br>Phosphorus                      | Low   | No  |   |  |

| Waterbody Name            | Waterbody<br>Size<br>(Acres) | Specific Pollutant or Stressor                     | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments |
|---------------------------|------------------------------|--|---|---|---|----------|
| GREAT SALT LAKE BASIN     |                              |  |   |   |   |          |
| BEAR RIVER DRAINAGE       |                              |  |   |   |   |          |
| Birch Creek Reservoir #2  | 63                           | Total Phosphorus, pH, Dissolved<br>Oxygen          | Low   | No  |   |          |
| Hyrum Reservoir           | 438                          | Total Phosphorus, Dissolved<br>Oxygen, Temperature | Low   | No  |   |          |
| Mantua Reservoir          | 554                          | Total Phosphorus, Dissolved<br>Oxygen, pH          | High  | Yes   |   |          |
| Newton Reservoir          | 350                          | Dissolved Oxygen, Total<br>Phosphorus, Temperature | Low   | No  |   |          |
| Porcupine Reservoir       | 190                          | Dissolved Oxygen, pH                               | Low   | No  |   |          |
| Tony Grove Lake           | 25                           | Dissolved Oxygen                                   | Low   | No  |   |          |
| Woodruff Creek Reservoir  | 90                           | рН   | Low   | No  |   |          |
| GREAT SALT LAKE BASIN     |                              |  |   |   |   |          |
| SEVIER RIVER DRAINAGE     |                              |  |   |   |   |          |
| Barney Reservoir          | 19                           | Total Phosphorus, Temperature,<br>Dissolved Oxygen | Low   | No  |   |          |
| Gunnison Reservior        | 1,287                        | Total Phosphorus, Dissolved<br>Oxygen              | Low   | No  |   |          |
| Kents Lake                | 26                           | Total Phosphorus, Dissolved<br>Oxygen, pH          | Low   | No  |   |          |
| Koosharem Reservoir       | 310                          | Total Phosphorus, Dissolved<br>Oxygen              | Low   | No  |   |          |
| LaBaron Reservoir         | 24                           | Dissolved Oxygen, pH                               | Low   | No  |   |          |
| Lower Box Creek Reservoir | 50                           | Dissolved Oxygen, pH, Total<br>Phosphorus          | Low   | No  |   |          |
| Manning Meadow Reservoir  | 59                           | Dissolved Oxygen                                   | Low   | No  |   |          |

| Waterbody Name                    | Waterbody<br>Size<br>(Acres) | Specific Pollutant or Stressor                                | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments |
|-----------------------------------|------------------------------|---|---|---|---|----------|
| Minersville Reservoir             | 990                          | Total Phosphorus, Dissolved<br>Oxygen, Temperature            | Low   | No  |   |          |
| New Castle Reservoir              | 163                          | Total Phosphorus, Dissolved<br>Oxygen, Temperature            | Low   | No  |   |          |
| Nine Mile Reservoir               | 197                          | Total Phosphorus, Dissolved<br>Oxygen, Temperature            | Low   | No  |   |          |
| Palisades Reservoir               | 66                           | Temperature, pH, Dissolved<br>Oxygen                          | Low   | No  |   |          |
| Otter Creek Reservoir             | 2,520                        | Total Phosphorus, Dissolved<br>Oxygen                         | Low   | No  |   |          |
| Panquitch Lake                    | 1,248                        | Total Phosphorus, Dissolved<br>Oxygen                         | Low   | No  |   |          |
| Pine Lake                         | 77                           | Dissolved Oxygen, pH  | Low   | No  |   |          |
| Puffer Lake                       | 65                           | Dissolved Oxygen  | Low   | No  |   |          |
| Red Creek Reservoir (Iron County) | 39                           | Dissolved Oxygen, Total<br>Phosphorus                         | Low   | No  |   |          |
| Rexs Reservoir                    | 46                           | Dissolved Oxygen  | Low   | No  |   |          |
| Three Creeks Reservoir            | 25                           | Temperature, pH   | Low   | No  |   |          |
| Tropic Reservoir                  | 180                          | Dissolved Oxygen, pH  | Low   | No  |   |          |
| Upper Enterprise Reservoir        | 200                          | Total Phosphorus, Dissolved<br>Oxygen, Temperature            | Low   | No  |   |          |
| Yankee Meadow Reservoir           | 5                            | рН  | Low   | No  |   |          |
| GREAT SALT LAKE BASIN             |                              |   |   |   |   |          |
| JORDAN RIVER DRAINAGE             |                              |   |   | •   |   |          |
| Decker Lake                       | ***                          | Total Phosphorus, Dissolved<br>Oxygen, Total Suspended Solids | Low   | No  |   |          |
| Lake Mary                         | 23                           | рН  | Low   | No  |   |          |

| Waterbody Name             | Waterbody<br>Size<br>(Acres) | Specific Pollutant or Stressor                     | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments |
|----------------------------|------------------------------|--|---|---|---|----------|
| Little Dell Reservoir      | 249                          | Temperature  | Low   | No  |   |          |
| UPPER COLORADO RIVER       |                              |  |   |   |   |          |
| GREEN RIVER DRAINAGE       |                              |  |   |   |   |          |
| Bridger Lake               | 21                           | Dissolved Oxygen, Temperature                      | Low   | No  |   |          |
| Brough Reservoir           | 150                          | Total Phosphorus, Dissolved<br>Oxygen, Temperature | Low   | No  |   |          |
| Browne Reservoir           | 54                           | Total Phosphorus, Dissolved<br>Oxygen              | Low   | No  |   |          |
| Calder Reservoir           | 99                           | pH. Dissolved Oxygen, Total<br>Phosphorus          | Low   | No  |   |          |
| China Reservoir            | 47                           | Dissolved Oxygen, pH.                              | Low   | No  |   |          |
| Cleveland Reservoir        | 185                          | Dissolved Oxygen                                   | Low   | No  |   |          |
| Duck Fork Reservoir        | 47                           | Dissolved Oxygen                                   | Low   | No  |   |          |
| Electric Lake Reservoir    | 425                          | Dissolved Oxygen                                   | Low   | No  |   |          |
| Fairview Reservoir         | 105                          | Dissolved Oxygen                                   | Low   | No  |   |          |
| Ferron Reservoir           | 55                           | Dissolved Oxygen                                   | Low   | No  |   |          |
| Fish Lake                  | 2,500                        | Dissolved Oxygen                                   | Low   | No  |   |          |
| Forsyth Reservoir          | 158                          | Total Phosphorus, Dissolved<br>Oxygen              | Low   | No  |   |          |
| Huntington Reservoir       | 115                          | Dissolved Oxygen, pH                               | Low   | No  |   |          |
| Johnson Reservoir          | 285                          | Total Phosphorus, Dissolved<br>Oxygen              | Low   | No  |   |          |
| Lower Gooseberry Reservoir | 57                           | Total Phosphorus, Dissolved<br>Oxygen              | Low   | No  |   |          |
| Lyman Lake                 | 27                           | Dissolved Oxygen                                   | Low   | No  |   |          |
| Marsh Lake                 | 38                           | Dissolved Oxygen                                   | Low   | No  |   |          |

| Waterbody Name                        | Waterbody<br>Size<br>(Acres) | Specific Pollutant or Stressor             | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments |
|---------------------------------------|------------------------------|--|---|---|---|----------|
| Matt Warner Reservoir                 | 433                          | Dissolved Oxygen, Total<br>Phosphorus      | Low   | No  |   |          |
| Mill Meadow Reservoir                 | 156                          | Total Phosphorus, Dissolved<br>Oxygen      | Low   | No  |   |          |
| Mirror Lake                           | 50                           | Dissolved Oxygen                           | Low   | No  |   |          |
| Pelican Lake                          | 1,680                        | Total Phosphorus, Dissolved<br>Oxygen, pH  | High  | Yes   |   |          |
| Red Creek Reservoir (Duchesne County) | 39                           | Dissolved Oxygen, Temperature              | Low   | No  |   |          |
| Scofield Reservoir                    | 2,815                        | Total Phosphorus, Dissolved<br>Oxygen      | High  | Yes   |   |          |
| Sheep Creek Reservoir                 | 86                           | Dissolved Oxygen                           | Low   | No  |   |          |
| Steinaker Reservoir                   | 829                          | Temperature                                | Low   | No  |   |          |
| Strawberry Reservoir                  | 17,160                       | Dissolved Oxygen, Total<br>Phosphorus, pH. | Low   | No  |   |          |
| LOWER COLORADO RIVER BASIN            |                              |  |   |   |   |          |
| VIRGIN RIVER DRAINAGE                 |                              |  |   |   |   |          |
| Baker Dam                             | 63                           | Total Phosphorus, Dissolved<br>Oxygen      | Low   | No  |   |          |
| Gunlock Reservoir                     | 266                          | Dissolved Oxygen                           | Low   | No  |   |          |
| Kolob Reservoir                       | 355                          | Total Phosphorus, Dissolved<br>Oxygen      | Low   | No  |   |          |
| Navajo Lake                           | 714                          | Dissolved Oxygen                           | Low   | No  |   |          |
| Quail Creek Reservoir                 | 590                          | Dissolved Oxygen                           | Low   | No  |   |          |

| Waterbody Name             | Waterbody<br>Size<br>(Acres) | Specific Pollutant or Stressor           | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments |
|----------------------------|------------------------------|--|---|---|---|----------|
| UPPER COLORADO RIVER BASIN |                              |  |   |   |   |          |
| COLORADO RIVER DRAINAGE    |                              |  |   |   |   |          |
| Blanding Reservoir         | 32                           | Dissolved Oxygen, pH                     | Low   | No  |   |          |
| Cook Lake                  | 9                            | Dissolved Oxygen                         | Low   | No  |   |          |
| Dark Canyon Reservoir      | 6                            | Dissolved Oxygen                         | Low   | No  |   |          |
| Kens Lake                  | 86                           | Temperature, pH                          | High  | Yes   |   |          |
| Lower Bowns Reservoir      | 90                           | Dissolved Oxygen                         | Low   | No  |   |          |
| Posey Lake                 | 20                           | Dissolved Oxygen                         | Low   | No  |   |          |
| Lloyds Reservoir           | 104                          | Dissolved Oxygen                         | Low   | No  |   |          |
| Recapture Creek Reservoir  | 265                          | Total Phosphorus, DO,<br>Temperature, pH | Low   | No  |   |          |
| Wide Hollow Reservoir      | 145                          | Temperature, pH                          | Low   | No  |   |          |

Table 1-b. Utah's 1998 303(d) List of Stream and River Waterbodies Identified as Needing Total Maximum Daily Load Analyses (TMDLs).

| Waterbody Name  | Waterbody<br>Size<br>(Miles) | Specific Pollutant or Stressor  | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number of<br>UPDES<br>Permit<br>Renewals | Comments |
|---|------------------------------|---|---|---|--|----------|
| GREAT SALT LAKE BASIN   |                              |   |   |   |  |          |
| UTAH LAKE DRAINAGE  |                              |   |   |   |  |          |
| <b>Diamond Fork Creek,</b><br>from confluence w/Spanish Fork River to<br>Sixth Water confluence | 19.4                         | Flow Alteration, Riparian Habitat<br>Alteration, Stream Habitat<br>Alteration | Low   | No  |  |          |
| Sixth Water Creek-tribs<br>confluence w/Diamond Fork to headwaters                              | 12.4                         | Flow Alteration, Riparian Habitat<br>Alteration, Stream Habitat<br>Alteration | Low   | No  |  |          |
| <b>Ironton Canal,</b><br>Utah Lake to heawaters   | 1.6                          | Hydrogen Sulfide  | Low   | No  |  |          |
| GREAT SALT LAKE BASIN   |                              |   |   |   |  |          |
| WEBER RIVER DRAINAGE  |                              |   |   |   |  |          |
| East Canyon Creek,<br>East Canyon Reservoir to headwaters                                       | 30.7                         | Total Phosphorus, Dissolved<br>Oxygen   | High  | Yes   |  |          |
| Echo Creek-tribs,<br>confluence w/ Weber R. to headwaters                                       | 43.0                         | Sediments   | Low   | No  |  |          |
| Silver Creek-tribs,<br>confluence w/ Weber River to headwaters                                  | 21.4                         | Zinc  | Low   | No  |  |          |
| GREAT SALT LAKE BASIN   |                              |   |   |   |  |          |
| FARMINGTON BAY AREA (GSL)   |                              |   |   |   |  |          |
| Settlement Canyon Creek and tributaries   | ***                          | Sediment, Metals  | Low   | No  |  |          |

| Waterbody Name  | Waterbody<br>Size<br>(Miles) | Specific Pollutant or Stressor  | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number of<br>UPDES<br>Permit<br>Renewals | Comments                 |
|---|------------------------------|---|---|---|--|--------------------------|
| GREAT SALT LAKE BASIN   |                              |   |   |   |  |                          |
| BEAR RIVER DRAINAGE   |                              |   |   |   |  |                          |
| Little Bear River,<br>Cutler Reservoir to Hyrum Reservoir   | 28.1                         | Total Phosphorus, Hydrological<br>Modification                              | High  | Yes   |  |                          |
| Little Bear River,<br>Hyrum Reservoir to East Fork Little Bear<br>confluence  | 6.8                          | Total Phosphorus  | High  | Yes   |  |                          |
| <b>Bear River,</b> Great Salt Lake to Malad River confluence  | 32.1                         | Total Phosphorus  | Low   | No  |  |                          |
| Bear River,<br>Malad River confluence to Cutler Reservoir   | 38.6                         | Total Phosphorus  | Low   | No  |  |                          |
| GREAT SALT LAKE BASIN   |                              |   |   |   |  |                          |
| SEVIER RIVER DRAINAGE   |                              |   |   |   |  |                          |
| <b>Beaver River-tribs,</b><br>Minersville to headwaters   | ***                          | Total Phosphorus, Noxious<br>Aquatic Plants, Riparian Habitat<br>Alteration | Low   | No  |  | Non Point Source Project |
| Sevier River-3, Sevier River-tribs: from Circleville to Circleville Canyon  | 19.72                        | Total Phosphorus, Sediment,<br>Habitat Aleration                            | Low   | No  |  |                          |
| Sevier River-10,<br>Sevier River from From Vermillion upstream<br>to Annabelle Diversion, includes tribs from<br>confluence w/Sevier River to USFS<br>boundary. | 23.20                        | Total Dissolved Solids  | Low   | No  |  |                          |
| Salina Creek-1,<br>Salina Creek-tribs; from confluence w/Sevier<br>River to USFS boundary   | 4.60                         | Total Dissolved Solids  | Low   | No  |  |                          |
| Lost Creek-1. Lost Creek-tribs: from confluence w/Ssevier River upstream 4 miles.   | 5.70                         | Total Dissolved Solids  | Low   | No  |  |                          |

| Waterbody Name   | Waterbody<br>Size<br>(Miles) | Specific Pollutant or Stressor   | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number of<br>UPDES<br>Permit<br>Renewals | Comments |
|--|------------------------------|--|---|---|--|----------|
| Sevier River-14,<br>Sevier River-tribs: from Sevier Bridge<br>Reservoir to Salina Creek confluence<br>(excluding Willow Creek and Sanpitch River)  | 73.27                        | Total Dissolved Solids, Sediment,<br>Total Phosphorus                        | Low   | No  |  |          |
| San Pitch-1,<br>San Pitch River-tribs: from confluence<br>w/Sevier River to tailwater of Gunnison<br>Reservoir (excluding all of Six Mile Creek &<br>Twelve Mile Creek above USFS boundary | 16.88                        | Total Dissolved Solids   | Low   | No  |  |          |
| San Pitch-3,<br>San Pitch River-tribs: from Gunnison<br>Reservoir to U132 crossing   | 32.32                        | Total Dissolved Solids   | Low   | No  |  |          |
| Chicken Creek-2,<br>Chicken Creek-tribs: from confluence<br>w/Sevier River to Levan  | 5.66                         | Total Dissolved Solids   | Low   | No  |  |          |
| Sevier River-15,<br>Sevier River-tribs: from Gunnison Bend<br>Reservoir to Sevier Bridge Reservoir<br>(excludes Chicken Creek and tribs withn<br>USFS boundary)                            | 121.97                       | Total Dissolved Solids, Sediment,<br>Habitat Alteration, Total<br>Phosphorus | Low   | No  |  |          |

| Waterbody Name   | Waterbody<br>Size<br>(Miles) | Specific Pollutant or Stressor                  | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number of<br>UPDES<br>Permit<br>Renewals | Comments                 |
|--|------------------------------|---|---|---|--|--------------------------|
| GREAT SALT LAKE BASIN  |                              |   |   |   |  |                          |
| JORDAN RIVER DRAINAGE  |                              |   |   |   |  |                          |
| Mill Creek,<br>I-15 to Forest Service Boundary                                 | 8.9                          | Fecal Coliform, Sediment, Habitat<br>Alteration | Low   | No  |  | Non Point Source Project |
| Mill Creek,<br>USFS Boundary to headwaters-tribs                               | 14.4                         | Fecal Coliform, Sediment, Habitat<br>Alteration | Low   | No  |  | Non Point Source Project |
| <b>Big Cottonwood Creek</b> ,<br>Jordan River to Forest Service Boundary       | 9.8                          | Copper  | Low   | No  |  |                          |
| Little Cottonwood Creek, confluence<br>Jordan River to Forest Service Boundary | 10.9                         | Total Dissolved Solids                          | Low   | No  |  |                          |
| Little Cottonwood Creek, Metropolitan WTP to headwaters-tribs                  | 24.5                         | Zinc  | Low   | No  |  |                          |
| <b>Jordan River</b> ,<br>6400 S to 7800 S                                      | 2.0                          | Total Dissolved Solids                          | High  | Yes   |  |                          |
| <b>Jordan River</b> ,<br>7800 S to Bluffdale                                   | 14.3                         | Total Dissolved Solids                          | High  | Yes   |  |                          |
| Bingham Creek,<br>confluence w/ Jordan River to<br>headwaters-tribs            | 12.9                         | Copper, Zinc, Total Dissolved<br>Solids         | Low   | No  |  |                          |
| <b>Jordan River</b> ,<br>Bluffdale to Narrows                                  | 4.2                          | Total Dissolved Solids                          | High  | Yes   |  |                          |
| <b>Jordan River</b> ,<br>Narrows to Utah Lake                                  | 12.0                         | Total Dissolved Solids                          | High  | Yes   |  |                          |
| <b>Parley's Creek</b> from 13th East to Little Dell<br>Reservoir               | ***                          | Hydrologic Modification                         | Low   | No  |  |                          |

| Waterbody Name   | Waterbody<br>Size<br>(Miles) | Specific Pollutant or Stressor                                 | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number of<br>UPDES<br>Permit<br>Renewals | Comments |
|--|------------------------------|--|---|---|--|----------|
| UPPER COLORADO RIVER   | UPPER COLORADO RIVER         |  |   |   |  |          |
| GREEN RIVER DRAINAGE   |                              |  |   |   |  |          |
| Price River,<br>from Water Treatment Plant to Scofield<br>Reservoir                              | ***                          | Total Suspended Solids   | High  | Yes   |  |          |
| Rock Creek,<br>from Green River to headwaters  | ***                          | Temperature, Total Dissolved<br>Solids, Total Suspended Solids | Low   | No  |  |          |
| Lake Fork-2, Lake Fork River tribs: from confluence w/Duschesne River to Pigeon Creek confluence | 30.87                        | Habitat Alteration   | Low   | No  |  |          |
| Indian Canyon Creek, Indian Canyon Creek-tribs: from confluence Duchesne River to headwaters     | 44.38                        | Total Dissolved Solids   | Low   | No  |  |          |
| Antelope Creek, Antelope Creek-tribs: from confluence w/Duchesne River to headwaters             | 31.38                        | Total Dissolved Solids   | Low   | No  |  |          |
| Deep Creek, Deep Creek-tribs: confluence Uintah River to headwaters                              | 24.73                        | Total Dissolved Solids   | Low   | No  |  |          |
| Uinta River-3,<br>Uinta River-tribs: from beneficial use change<br>USFS boundary                 | 75.42                        | Flow Alteration, Habitat<br>Alteration                         | Low   | No  |  |          |
| Uinta River-2,<br>Uinta River: from 9 miles from mouth to<br>change in beneficial use            | 3.16                         | Total Dissolved Solids, Habitat<br>Alteration                  | Low   | No  |  |          |
| Duchesne River-1, Duchesne River-tribs: from confluence w/Green River to Randlett.               | 19.14                        | Total Dissolved Solids   | Low   | No  |  |          |
| Dry Gulch Creek, Dry Gulch Creek-tribs: from confluence w/Uinta River to headwaters.             | 87.67                        | Total Dissolved Solids   | High  | Yes   |  |          |
| Pariette Draw, Pariette Draw-tribs: from cofluence w/Green River to headwaters                   | 54.13                        | Total Dissolved Solids, Boron                                  | Low   | No  |  |          |

| Waterbody Name   | Waterbody<br>Size<br>(Miles) | Specific Pollutant or Stressor                   | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number of<br>UPDES<br>Permit<br>Renewals | Comments |
|--|------------------------------|--|---|---|--|----------|
| Willow Creek,<br>Willow Creek-tribs: from confluence w/Green<br>River to Meadow Creek confluence | 57.54                        | Total Dissolved Solids                           | Low   | No  |  |          |
| Uinta River-1,<br>Uinta River-tribs: from confluence w/Duchesne<br>upstream about 9 miles        | 8.82                         | Total Dissolved Solids,<br>Temperature, Sediment | High  | Yes   |  |          |
| Lake Fork-1, Lake Fork-tribs: from confluence w/Duchesne River to Pigeon Water Creek confluence  | 22.36                        | Sediment, Temperature                            | Low   | No  |  |          |
| Nine Mile Creek, Nine Mile Creek-tribs: from confluence w/Green River to headwaters              | 118.89                       | Temperature                                      | Low   | No  |  |          |
| Lower Ashley Creek,<br>Ashley Creek-tribs: from confluence w/Green<br>River upstream 16 miles    | 15.19                        | Selenium, Total Dissolved Solids                 | Low   | No  |  |          |
| Duchesne River-2, Duchesne River from Randlett to Myton.   | 31.82                        | Total Dissolved Solids                           | Low   | No  |  |          |

| Waterbody Name  | Waterbody<br>Size<br>(Miles) | Specific Pollutant or Stressor | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number of<br>UPDES<br>Permit<br>Renewals | Comments |
|---|------------------------------|--------------------------------|---|---|--|----------|
| LOWER COLORADO RIVER BASIN  |                              |                                |   |   |  |          |
| VIRGIN RIVER DRAINAGE   |                              |                                |   |   |  |          |
| <b>Virgin River-1</b><br>Virgin River from state line to Santa Clara  | ***                          | Total Dissolved Solids         | Low   | No  |  |          |
| Virgin River-2 Virgin River-tribs from Santa Clara confluence to Laverkin Creek confluence (except Quail Creek and Leeds Creek) | ***                          | Total Dissolved Solids         | Low   | No  |  |          |
| Beaver Dam Wash-tribs:<br>from Motoqua to headwaters  | ***                          | Temperature                    | Low   | No  |  |          |
| North Creek-tribs<br>from confluence with Virgin River to<br>headwaters   | ***                          | Total Dissolved Solids         | Low   | No  |  |          |
| Santa Clara-1<br>Santa Clara River from confluence w/ Virgin<br>River Gunlock Reservoir   | ***                          | Temperature, Sediment          | Low   | No  |  |          |
| LOWER COLORADO RIVER BASIN  |                              |                                |   |   |  |          |
| KANAB DRAINAGE  | KANAB DRAINAGE               |                                |   |   |  |          |
| Kanab Creek-2<br>Kanab Creek-tribs from Reservoir Canyon to<br>headwaters   | ***                          | Temperature                    | Low   | No  |  |          |

| Waterbody Name   | Waterbody<br>Size<br>(Miles) | Specific Pollutant or Stressor                                    | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number of<br>UPDES<br>Permit<br>Renewals | Comments  |
|--|------------------------------|---|---|---|--|---|
| UPPER COLORADO RIVER BASIN   |                              |   |   |   |  |   |
| COLORADO RIVER DRAINAGE  | <u> </u>                     |   | 1   | 1   | 1  |   |
| Paria River,<br>from stateline to headwaters-tribs                             | ***                          | Total Dissolved Solids, Sediment                                  | Low   | No  |  | Intensive Survey being conducted in this area. There is a high probability that the waterbodies will be changed to reflect different stream types and ecological differences. |
| Escalante River,<br>from Lake Powell to Calf Creek                             | ***                          | Total Phosphorus, Sediment  | Low   | No  |  | Intensive Survey being conducted in this area. There is a high probability that the waterbodies will be changed to reflect different stream types and ecological differences. |
| Escalante River, from confluence of Calf Creek to headwaters                   | ***                          | Sediment  | Low   | No  |  | Intensive Survey being conducted in this area. There is a high probability that the waterbodies will be changed to reflect different stream types and ecological differences. |
| Calf Creek,<br>confluence w/ Escalante River to headwaters                     | ***                          | Temperature, Total Dissolved<br>Solids, Sediment                  | Low   | No  |  | Intensive Survey being conducted in this area. There is a high probability that the waterbodies will be changed to reflect different stream types and ecological differences. |
| San Juan,<br>San Juan River (with exceptions) from Lake<br>Powell to stateline | ***                          | Lead, Copper, Zinc, Total<br>Dissolved Solids, Sediment           | Low   | No  |  | Intensive Survey being conducted in this area. There is a high probability that the waterbodies will be changed to reflect different stream types and ecological differences. |
| <b>Montezuma Creek</b> , from San Juan River to headwaters-tribs               | ***                          | Dissolved Oxygen, Lead, Zinc,<br>Total Dissolved Solids, Sediment | Low   | No  |  | Intensive Survey being conducted in this area. There is a high probability that the waterbodies will be changed to reflect different stream types and ecological differences. |

| Waterbody Name   | Waterbody<br>Size<br>(Miles) | Specific Pollutant or Stressor                         | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number of<br>UPDES<br>Permit<br>Renewals | Comments  |
|--|------------------------------|--|---|---|--|---|
| Verdure Creek,<br>from Montezuma Creek to headwaters                               | ***                          | Total Dissolved Solids, Sediment                       | Low   | No  |  | Intensive Survey being conducted in this area. There is a high probability that the waterbodies will be changed to reflect different stream types and ecological differences. |
| North Creek,<br>from Montezuma to headwaters                                       | ***                          | Total Dissolved Solids, Sediment                       | Low   | No  |  | Intensive Survey being conducted in this area. There is a high probability that the waterbodies will be changed to reflect different stream types and ecological differences. |
| South Creek,<br>from Montezuma to headwaters                                       | ***                          | Total Dissolved Solids, Sediment                       | Low   | No  |  | Intensive Survey being conducted in this area. There is a high probability that the waterbodies will be changed to reflect different stream types and ecological differences. |
| Spring Creek,<br>from Vega Creek (tributaries to Montezuma)<br>to headwaters       | ***                          | Total Dissolved Solids, Sediment                       | Low   | No  |  | Intensive Survey being conducted in this area. There is a high probability that the waterbodies will be changed to reflect different stream types and ecological differences. |
| <b>Delores River</b> , from confluence with Colorado River to stateline-tribs      | ***                          | Total Dissolved Solids, Iron,<br>Ammonia, Sediment     | Low   | No  |  | Intensive Survey being conducted in this area. There is a high probability that the waterbodies will be changed to reflect different stream types and ecological differences. |
| <b>Dirty Devil River,</b><br>from Lake Powell to Muddy/Fremont River<br>confluence | ***                          | Total Dissolved Solids, Sediment                       | Low   | No  |  | Intensive Survey being conducted in this area. There is a high probability that the waterbodies will be changed to reflect different stream types and ecological differences. |
| Fremont River,<br>from Muddy to Capital Reef N.P. east<br>boundary                 | ***                          | Total Dissolved Solids,<br>Temperature, Sediment, Iron | Low   | No  |  | Intensive Survey being conducted in this area. There is a high probability that the waterbodies will be changed to reflect different stream types and ecological differences. |

| Waterbody Name  | Waterbody<br>Size<br>(Miles) | Specific Pollutant or Stressor                         | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number of<br>UPDES<br>Permit<br>Renewals | Comments  |
|---|------------------------------|--|---|---|--|---|
| Fremont River,<br>from Capital Reef east boundary to Mill<br>Meadow Reservoir | ***                          | Total Dissolved Solids,<br>Temperature, Iron, Sediment | Low   | No  |  | Intensive Survey being conducted in this area. There is a high probability that the waterbodies will be changed to reflect different stream types and ecological differences. |
| Fremont River,<br>from Mill Meadow Reservoir to Johnson<br>Reservoir          | ***                          | Total Dissolved Solids, Sediment                       | Low   | No  |  | Intensive Survey being conducted in this area. There is a high probability that the waterbodies will be changed to reflect different stream types and ecological differences. |
| Muddy Creek,<br>from confluence with Fremont River to U-10<br>crossing        | ***                          | Total Dissolved Solids, Sediment                       | Low   | No  |  | Intensive Survey being conducted in this area. There is a high probability that the waterbodies will be changed to reflect different stream types and ecological differences. |
| Muddy Creek,<br>from U-10 to headwaters                                       | ***                          | Total Dissolved Solids, Sediment                       | Low   | No  |  | Intensive Survey being conducted in this area. There is a high probability that the waterbodies will be changed to reflect different stream types and ecological differences. |

Table 1-c. Utah's 1998 303(d) List of Receiving Waters with Utah Pollution

Discharge Elimination System Discharge Permit Renewals Needing Total

Maximum Daily Load

Analyses (TMDLs).

| Waterbody Name (Receiving Water) Permittee UPDES Permit Number Date of Permit Renewal | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)  | Priority<br>for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments   |
|---|------------------------------------|--|--|---|---|--|
| GREAT SALT LAKE BASIN   |                                    |  |  |   |   |  |
| UTAH LAKE DRAINAGE  Snake Creek  Midway Fish Hatchery UT0025194 02/28/00              | **                                 | pH, Total Phosphorus, Total<br>Suspended Solids  | High   | Yes   | 1   | Receiving water not listed as impaired.  |
| Utah Lake<br>Orem City Corp<br>UT0020915<br>03/31/99                                  | **                                 | BOD, Fecal Coliform, Total<br>Coliform, Ammonia, Oil and<br>Grease, pH, Total Suspended<br>Solids  | High   | Yes   | 1   | Receiving water listed as impaired for total phosporus, total dissolved solids, and trophic state index. |
| Utah Lake<br>Geneva Steel<br>UT000036<br>09/30/99                                     | **                                 | Benzene, Benzo(a)pyrene, BOD,<br>Chlorine Residual, Fecal<br>Coliform, Total Coliform,<br>Cyanide, Lead, Napthalene,<br>Ammonia, Oil and Grease, pH,<br>Phenolics, Total Dissolved<br>Solids, Total Suspended Solids | High   | Yes   | 1   | Receiving water listed as impaired for total phosporus, total dissolved solids, and trophic state index. |
| Mill Race Creek<br>Provo City Corp<br>UT0021717<br>12/31/98                           | **                                 | BOD, Chlorine Residual, Fecal<br>Coliform, Total Coliform,<br>Ammonia, Oil and Grease,<br>Dissolved Oxygen, pH, Phenols,<br>Total Suspended Solids   | High   | Yes   | 1   | Receiving water listed as impaired for metals and hydrogen sulfide.                                      |
| Irrigation Ditch A. P. Green RE FractorIBS UT0021300 03/31/99                         | **                                 | pН   | High   | Yes   | 1   | Receiving water not listed as impaired.  |

<sup>\* -</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

<sup>\*\* -</sup> Stream segment lengths for TMDLs vary for each permit.

| Waterbody Name (Receiving Water) Permittee UPDES Permit Number Date of Permit Renewal | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)   | Priority<br>for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments   |
|---|------------------------------------|---|--|---|---|--|
| <b>Utah Lake</b><br>Timpanogos Special Service Dis<br>UT0023639<br>10/31/99           | **                                 | BOD, Cadmium, Chlorine<br>Residual Fecal Coliform, Total<br>Coliform, Ammonia, Oil and<br>Grease, pH, Total Suspended<br>Solids | High   | Yes   | 1   | Receiving water listed as impaired for total phosporus, total dissolved solids, and trophic state index. |
| GREAT SALT LAKE BASIN WEBER RIVER DRAINAGE  |                                    |   |  |   |   |  |
| Ditch-> Dry Creek Plain City Corporation UT0021326 12/31/98                           | **                                 | BOD, Chlorine Residual, Fecal<br>Coliform, Total Coliform, pH,<br>Total Suspended Solids  | High   | Yes   | 1   | Receiving water not listed as impaired.  |
| Easy Canyon<br>Snyderville Basin Sewer Imp. District<br>UT0020001                     | **                                 | Bod Chlorine Residual, Fecal<br>Coliform, Total Coliform, pH,<br>Total Suspended Solids,<br>Ammonia                             | High   | Yes   | 1   | Receiving water listed as impaired for total phophorus and dissolved oxygen.                             |
| Weber River Mountain Green Sewer District UT0024732 03/31/00                          | **                                 | BOD, Chlorine Residual, Fecal<br>Coliform, Total Coliform, pH,<br>Total Suspended Solids  | High   | Yes   | 1   | Receiving water not listed as impaired.  |
| Lost Creek<br>Holnam Inc. (Ideak Basic)<br>UT0000159<br>07/31/98                      | **                                 | Chlorine Residual, Temperature,<br>Flow, Oil and Grease, pH, Total<br>Suspended Solids  | High   | Yes   | 1   | Receiving water not listed as impaired.  |
| Weber River<br>Henefer<br>UT0020192<br>10/31/99                                       | **                                 | BOD, Fecal Coliform, Total<br>Coliform, Dissolved Oxygen,<br>pH, Total Suspended Solids   | High   | Yes   | 1   | Receiving water not listed as impaired.  |

<sup>\* -</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

 $<sup>\</sup>ensuremath{^{**}}$  - Stream segment lengths for TMDLs  $% \ensuremath{^{**}}$  vary for each permit.

| Waterbody Name (Receiving Water) Permittee UPDES Permit Number Date of Permit Renewal        | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)   | Priority<br>for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                                |
|--|------------------------------------|---|--|---|---|---|
| <b>Ditch-&gt; Hooper Canal-&gt; Weber River</b> Farmers Grain Cooperative UT0025135 05/31/99 | **                                 | BOD, Flow, Wet Test, pH,<br>Total Suspended Solids,<br>Trichloroethene                                      | High   | Yes   | 1   | Receiving water not listed as impaired. |
| Chalk Creek<br>Coalville City Corp<br>UT0021288<br>08/31/99                                  | **                                 | BOD, Fecal Coliform, Total<br>Coliform, Ammonia, pH, Total<br>Suspended Solids                              | High   | Yes   | 1   |   |
| Great Salt Lake Basin  | Great Salt Lake Basin              |   |  |   |   |   |
| Farmington Bay Area (GSL)  |                                    |   |  |   |   |   |
| State Canal<br>S Davis Co SEWER North<br>UT0021636<br>06/30/98                               | **                                 | BOD, Chlorine Residual, Fecal<br>Coliform, Total Coliform, Oil<br>and Grease, pH, Total Suspended<br>Solids | High   | Yes   | 1   | Receiving water not listed as impaired. |
| Ditch-> Great Salt Lake<br>Central Davis Co SEWER<br>UT0020974<br>02/28/00                   | **                                 | BOD, Fecal Coliform, Total<br>Coliform, Oil and Grease, Wet<br>Test, pH, Total Suspended<br>Solids          | High   | Yes   | 1   | Receiving water not listed as impaired. |
| Stone Creek Air Products & Chemical Inc. UT0024210 09/30/98                                  | **                                 | Chlorine Residual, pH, Total<br>Dissolved Solids, Total<br>Suspended Solids                                 | High   | Yes   | 1   | Receiving water not listed as impaired. |

<sup>\* -</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

<sup>\*\* -</sup> Stream segment lengths for TMDLs vary for each permit.

| Waterbody Name (Receiving Water) Permittee UPDES Permit Number Date of Permit Renewal | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)   | Priority<br>for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                                |
|---|------------------------------------|---|--|---|---|---|
| GREAT SALT LAKE BASIN   |                                    |   |  |   |   |   |
| Blue Creek<br>Thiokol Corporation<br>UT0024805<br>02/28/99                            | **                                 | Aluminum, BOD, Chlorine<br>Residual, Fecal Coliform, Total<br>Coliform, Cyanide, Isopropanol,<br>Ammonia, Oil and Grease, Oil<br>and Grease, Wet Test, pH,<br>Silver, Total Dissolved Solids,<br>Total Suspended Solids, Volatile<br>Organics | High   | Yes   | 1   | Receiving water not listed as impaired. |
| Ditch-> Great Salt Lake<br>Lakepoint Improv Dist<br>UT002023<br>03/31/99              | **                                 | BOD, Fecal Coliform, Total<br>Coliform, pH, Total Suspended<br>Solids   | High   | Yes   | 1   | Receiving water not listed as impaired. |
| Blue Lakes<br>Grantsville City<br>UT0021130<br>01/31/99                               | **                                 | BOD, Fecal Coliform, Total<br>Coliform, Flow, pH, Total<br>Suspended Solids   | High   | Yes   | 1   | Receiving water not listed as impaired. |
| Eureka Creek Eureka City Corporation UT002460 07/31/99                                | **                                 | BOD,Fecal Coliform, Total<br>Coliform, Flow, pH, Total<br>Suspended Solids  | High   | Yes   | 1   | Receiving water not listed as impaired. |
| Unnamed Drainage-> Salt Flats Wendover City of UT0020745 11/30/99                     | **                                 | BOD, Fecal Coliform, Total<br>Coliform, pH, Total Suspended<br>Solids   | High   | Yes   | 1   | Receiving water not listed as impaired. |
| Great Salt Lake<br>AKZO Salt<br>UT0000639<br>12/31/98                                 | **                                 | Oil and Grease, pH  | High   | Yes   | 1   | Receiving water not listed as impaired. |

<sup>\* -</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

 $<sup>\</sup>ensuremath{^{**}}$  - Stream segment lengths for TMDLs  $% \ensuremath{^{**}}$  vary for each permit.

| Waterbody Name (Receiving Water) Permittee UPDES Permit Number Date of Permit Renewal | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)   | Priority<br>for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                                |
|---|------------------------------------|---|--|---|---|---|
| Great Salt Lake<br>Perry City<br>UT0021148<br>02/28/99                                | **                                 | BOD, Chlorine Residual, Fecal<br>Coliform, Total Coliform,<br>Ammonia, pH, Total Suspended<br>Solids                                      | High   | Yes   | 1   | Receiving water not listed as impaired. |
| GREAT SALT LAKE BASIN BEAR RIVER DRAINAGE   |                                    |   |  |   |   |   |
| Cutler Reservoir<br>Logan City Corporation<br>UT0021920<br>10/31/98                   | **                                 | BOD, Chlorine Residual, Fecal<br>Coliform, Total Coliform,<br>Ammonia, Oil and Grease,<br>Dissolved Oxygen, pH, Total<br>Suspended Solids | High   | Yes   | 1   |   |
| Ditch-> Blacksmith Fork River<br>Silicone Plastics<br>UT0025186<br>08/31/99           | **                                 | Oil and Grease, pH, Total<br>Suspended Solids   | High   | Yes   | 1   | Receiving water not listed as impaired. |
| Malad River Bear River Town of UT0020311 09/30/99                                     | **                                 | BOD, Chlorine Residual, Fecal<br>Coliform, Total Coliform, pH,<br>Total Suspended Solids,<br>Dissolved Oxygen                             | High   | Yes   | 1   | Receiving water not listed as impaired  |
| Bear River<br>Corinne City of<br>UT0020931<br>02/31/99                                | **                                 | Fecal Coliform, Total Coliform,<br>Flow, BOD, pH, Total<br>Suspended Solids   | High   | Yes   | 1   |   |
| Cub River<br>Richmond City of<br>UT0020907<br>09/30/98                                | **                                 | Fecal Coliform, Total Coliform,<br>Flow, BOD, pH, Total<br>Suspended Solids   | High   | Yes   | 1   |   |

<sup>\* -</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

<sup>\*\* -</sup> Stream segment lengths for TMDLs vary for each permit.

| Waterbody Name (Receiving Water) Permittee UPDES Permit Number Date of Permit Renewal         | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)   | Priority<br>for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                               |
|---|------------------------------------|---|--|---|---|--|
| Ditch-> Little Bear River<br>Hyrum City Corportation<br>UT0023205<br>05/30/98                 | **                                 | BOD, Chlorine Residual, Fecal<br>Coliform, Total Coliform, Oil<br>and Grease, pH, Total<br>Suspended Solids   | High   | Yes   | 1   |  |
| Blue Spring Drainage-> Cutler Reservoir<br>Gossner Foods Inc.<br>UT0024309<br>12/31/98        | **                                 | BOD, Temperature, Oil and<br>Grease, pH, Total Suspended<br>Solids  | High   | Yes   | 1   | Receiving water not listed as impaired |
| GREAT SALT LAKE BASIN JORDAN RIVER DRAINAGE   |                                    |   |  |   |   |  |
| Oil Drain Canal<br>Salt Lake City Corpwaste Water<br>UT0021725<br>09/30/98                    | **                                 | BOD, Chlorine Residual, Fecal<br>Coliform, Total Coliform, Oil<br>and Grease, pH,Total Suspended<br>Solids  | High   | Yes   | 1   | Receiving water not listed as impaired |
| City Drain-> Sewage Canal-> Great Salt<br>Lake<br>Unisys Corporation<br>UT0020397<br>04/30/99 | **                                 | 1,1,1-Trichloroethane, 1,1,2-<br>Trichloroethane,<br>1,1,-Dichloroethylene, 1,2-<br>Dichloroethane, Benzene, Oil<br>and Grease, Toxic Organics,<br>pH, Tetrachloroethene, Total<br>Agg. Concentration,<br>Trichloroethene, Vinyl Chloride | High   | Yes   | 1   | Receiving water not listed as impaired |
| Mill Creek<br>Central Valley Wtr Rfb Central<br>UT0024392<br>07/31/99                         | **                                 | BOD, Chlorine Residual, Fecal<br>Coliform, Total<br>Coliform,Ammonia, Oil and<br>Grease, Dissolved Oxygen, pH,<br>Total Suspended Solids  | High   | Yes   | 1   |  |

<sup>\* -</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

 $<sup>\</sup>ensuremath{^{**}}$  - Stream segment lengths for TMDLs  $% \ensuremath{^{**}}$  vary for each permit.

| Waterbody Name (Receiving Water) Permittee UPDES Permit Number Date of Permit Renewal  | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)   | Priority<br>for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                               |
|--|------------------------------------|---|--|---|---|--|
| City Drain Surplus Canal Salt Lake City Intrntnl Airprt UT0024988 03/31/99   | **                                 | 1,2-Propanediol, BOD, Ethylene<br>Glycol, Flow, Nitrite - Nitrate,<br>Oil and Grease, COD, pH   | High   | Yes   | 1   | Receiving water not listed as impaired |
| South Salt Lake Storm Drains-> Jordan<br>River<br>Rubber Engineering<br>UT0024767<br>01/31/99  | **                                 | BOD,Oil and Grease, pH, Total<br>Suspended Solids   | High   | Yes   | 1   |  |
| C-7 Ditch Pine Canyon Creek Butterfield Creek Jordan River West C-7 Ditch Little Valley Wash Unnamed Drainage-> Great Salt Lake Kennecott Copper Co. UT000005 01/31/00 | **                                 | Arsenic, BOD, Cadmium, Fecal<br>Coliform, Total Coliform,<br>Copper, Cyanide, Lead,<br>Mercury, Nickel, Oil and<br>Grease, Wet Test, pH,<br>Phenolics, Total Dissolved<br>Solids,<br>Total Suspended Solids, Zinc | High   | Yes   | 1   | Receiving water not listed as impaired |

<sup>\* -</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

<sup>\*\* -</sup> Stream segment lengths for TMDLs vary for each permit.

| Waterbody Name (Receiving Water) Permittee UPDES Permit Number Date of Permit Renewal | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)  | Priority<br>for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                               |
|---|------------------------------------|--|--|---|---|--|
| Jordan River<br>Envirotech Pump System (BGA)<br>UT0025089<br>04/30/98                 | **                                 | Flow, Oil and Grease, pH   | High   | Yes   | 1   | Receiving water not listed as impaired |
| UPPER COLORADO RIVER BASIN  |                                    |  |  |   |   |  |
| GREEN RIVER DRAINAGE  |                                    |  |  |   |   |  |
| Big Wash<br>Denver American Petroleum<br>UT0000124<br>04/30/99                        | **                                 | BOD, Oil and Grease, pH, Total<br>Dissolved Solids, Total<br>Suspended Solids                        | High   | Yes   | 1   | Receiving water not listed as impaired |
| Cedar Creek<br>United States Fuel Co.<br>UT0023094<br>05/31/99                        | **                                 | Iron, Oil and Grease, pH, Total<br>Dissolved Solids, Total<br>Suspended Solids                       | High   | Yes   | 1   | Receiving water not listed as impaired |
| <b>700 West Ditch</b> Wasatch Chemical Site UT0025119 12/31/98                        | **                                 | BOD, pH, Total Suspended<br>Solids, Toxic Organics   | High   | Yes   | 1   | Receiving water not listed as impaired |
| Ferron Creek<br>Ferron City of<br>UT0020052<br>03/31/99                               | **                                 | BOD, Chlorine Residual, Fecal<br>Coliform, Total Coliform,<br>Ammonia, pH, Total Suspended<br>Solids | High   | Yes   | 1   | Receiving water not listed as impaired |
| Union Irrigation Canal<br>Equity Oil Co<br>UT0000035<br>04/30/99                      | **                                 | BOD, Total Suspended Solids,<br>Oil and Grease, pH, Total<br>Dissolved Solids                        | High   | Yes   | 1   | Receiving water not listed as impaired |

<sup>\* -</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

 $<sup>\</sup>ensuremath{^{**}}$  - Stream segment lengths for TMDLs  $% \ensuremath{^{**}}$  vary for each permit.

| Waterbody Name (Receiving Water) Permittee UPDES Permit Number Date of Permit Renewal | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)  | Priority<br>for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                               |
|---|------------------------------------|--|--|---|---|--|
| <b>Quitchupah Creek</b><br>Consol. Coal Co. Underground Mine<br>UT0022616<br>05/31/99 | **                                 | Oil and Grease, pH, Solids<br>Settleable, Total Dissolved<br>Solids, Total Suspended Solids                | High   | Yes   | 1   | Receiving water not listed as impaired |
| Eccles Creek UP Canyon Creek Canyon Fuel Co. LLC Skyline Ut UT0023540 09/30/99        | **                                 | Iron, Oil and Grease, Wet Test,<br>pH, Dissolved Solids, Total<br>Suspended Solids                         | High   | Yes   | 1   | Receiving water not listed as impaired |
| Cottonwood Creek<br>Castle Valley SSD(Huntington)<br>UT0021296<br>10/31/99            | **                                 | BOD, Fecal Coliform, Total<br>Coliform, Ammonia, pH, Total<br>Suspended Solids                             | High   | Yes   | 1   | Receiving water not listed as impaired |
| Union Irrigation Canal<br>Hollandsworth & Travis<br>UT0021792<br>04/30/99             | **                                 | BOD, Oil and Grease, pH, Total<br>Dissolved Solids, Total<br>Suspended Solids                              | High   | Yes   | 1   | Receiving water not listed as impaired |
| Union Irrigation Canal<br>United Utilities Corp.<br>UT0021768<br>04/30/99             | **                                 | BOD, Oil and Grease, pH, Total<br>Dissolved Solids, Total Suspended<br>Solids                              | High   | Yes   | 1   | Receiving water not listed as impaired |
| Price River Price City Water Treatment Plt UT0024589 07/31/99                         | **                                 | Aluminum, Chlorine Residual,<br>Dissolved Oxygen, pH, Total<br>Dissolved Solids, Total Suspended<br>Solids | High   | Yes   | 1   |  |

<sup>\* -</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

<sup>\*\* -</sup> Stream segment lengths for TMDLs vary for each permit.

| Waterbody Name (Receiving Water) Permittee UPDES Permit Number Date of Permit Renewal | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)   | Priority<br>for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                               |
|---|------------------------------------|---|--|---|---|--|
| LOWER COLORADO RIVER BASIN COLORADO RIVER DRAINAGE                                    |                                    |   |  |   |   |  |
| Hatch Wash->Kane Canyon Creek<br>U.S. Energy Velvet Mine<br>UT0023914<br>12/31/99     | **                                 | Oil and Grease, COD, pH,<br>Radium 226, Total Dissolved<br>Solids, Total Suspended Solids,<br>Uranium | High   | Yes   | 1   | Receiving water not listed as impaired |
| Montezuma Creek<br>Monticello City Stp<br>UT0024503<br>8/31/99                        | **                                 | BOD, Fecal Coliform, Total<br>Coliform, pH, Suspended Solids,<br>Total Suspended Solids               | High   | Yes   | 1   | Receiving water not listed as impaired |

<sup>\* -</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

<sup>\*\* -</sup> Stream segment lengths for TMDLs vary for each permit.

Table 1-d. Utah's 1998 303(d) List of Utah Pollution Discharge Ellimination

System Total Maximum Daily Load Analyses (TMDLs) Completed During the

1996-1998 Cycle. Completed TMDLs Will Be Removed When Approved by

EPA.

Table 1-d. Utah's 1998 303(d) List of Utah Pollution Discharge Elimnation System (UPDES) Permit Renewal Total Maximum Daily Load Analyses (TMDLs) Completed During the 1996-1998 Cycle. Completed TMDLs Will Be Removed When Approved by EPA.

| Waterbody Name (Receiving Water) Permittee Permit Number Date of Permit Renewal | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)   | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                               |
|---|------------------------------------|---|---|---|---|--|
| GREAT SALT LAKE BASIN   |                                    |   |   |   |   |  |
| UTAH LAKE DRAINAGE  |                                    |   |   |   |   |  |
| Ag. Ditch<br>Nephi Rubber<br>UT0025097<br>6/18/97                               | **                                 | pH Total Suspended Solids, Oil<br>& Grease, Flow  | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL approved by EPA. |
| Ironton Canal -> Utah Lake<br>Reilly Industries Inc.<br>UT0000370<br>6/3/97     | **                                 | Temperature, Flow, BOD, pH,<br>Total Suspended Solids, Oil &<br>Grease, pH, Phenolics,  | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL approved by EPA. |
| Ironton Canal -> Utah Lake Pacific States Cast Iron UT0000612 5/24/96           | **                                 | Temperature, Dissolved Oxygen,<br>BOD, Copper, Lead, Zinc, pH,<br>Phenols, Flow, Residual<br>Chlorine, Hydrogen Sulfide, Wet<br>Test, Total Suspended Solids, Oil<br>& Grease,  | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL approved by EPA. |
| Dry Creek<br>Spanish Fork<br>UT0020109<br>7/8/97                                | **                                 | Total Suspended Solids, Volatile<br>Solids, Arsenic, Selenium, Zinc,<br>Lead, Nickel, Mercury,<br>Chromium, Copper, Cadmium,<br>BOD, pH, Oil & Grease, Flow,<br>Chlorine Residual, Ammonia,<br>Fecal Coliform, Total Coliform,<br>Thallium, Silver, Antimony,<br>Phenols, Mercury, Wet Test | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL approved by EPA. |

<sup>\*-</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

<sup>\*\* -</sup> Stream segment lengths for TMDLs vary for each permit.

Table 1-d. Utah's 1998 303(d) List of Utah Pollution Discharge Elimnation System (UPDES) Permit Renewal Total Maximum Daily Load Analyses (TMDLs) Completed During the 1996-1998 Cycle. Completed TMDLs Will Be Removed When Approved by EPA.

| Waterbody Name (Receiving Water) Permittee Permit Number Date of Permit Renewal | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)   | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                               |
|---|------------------------------------|---|---|---|---|--|
| Beer Creek -> Utah Lake<br>Salem City Corp.<br>UT0020249<br>9/15/97             | **                                 | Dissolved Oxygen, BOD, pH,<br>Total Suspended Solids, Oil &<br>Grease, Ammonia, Flow,<br>Chlorine Residual, Fecal<br>Coliform, Total Coliform,<br>Suspended Solids  | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL approved by EPA. |
| Beer Creek Payson City Corp. UT0020417 9/30/97                                  | **                                 | Volatile Solids, Arsenic,<br>Selenium, Zinc, Lead, Mercury,<br>Chromium, Copper, Cadmium,<br>pH, Total Suspended Solids, Oil<br>& Grease, Ammonia, Flow,<br>Residual Chlorine, Fecal<br>Coliform, Total Coliform, BOD   | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL approved by EPA. |
| Spring Creek -> Utah Lake<br>Springville City<br>UT0020834<br>6/9/97            | **                                 | Volatile Solids, Arsenic, Selenium, Zinc, Lead, Nickel, Mercury, Chromium, Copper, Cadmium, Dissolved Oxygen pH, Total Suspended Solids, Oil & Grease, Flow, Residual Chlorine, Ammonia, Fecal Coliform, Total Coliform | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL approved by EPA. |
| Jordanelle Res.<br>United Park City Mines<br>UT0022403<br>6/24/97               | **                                 | Flow, pH, Total Suspended<br>Solids, Oil & Grease, Hardness,<br>Zinc, Lead, Copper, Mercury,<br>Oil & Grease Wet Test, Lead   | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL approved by EPA. |
| Class 6 Ditch -> Jordan River<br>PacifiCorp - Gadsby<br>UT0000116<br>11/25/96   | **                                 | pH, Total Suspended Solids, Oil<br>& Grease, Iron, Flow, Free<br>Chlorine   | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL approved by EPA. |

<sup>\*-</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

<sup>\*\* -</sup> Stream segment lengths for TMDLs vary for each permit.

Table 1-d. Utah's 1998 303(d) List of Utah Pollution Discharge Elimnation System (UPDES) Permit Renewal Total Maximum Daily Load Analyses (TMDLs) Completed During the 1996-1998 Cycle. Completed TMDLs Will Be Removed When Approved by EPA.

| Waterbody Name (Receiving Water) Permittee Permit Number Date of Permit Renewal | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)   | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                                  |
|---|------------------------------------|---|---|---|---|---|
| Ditch -> Oil Drain (6) -> GSL<br>Amoco HWMF<br>UT0025071                        | **                                 | Flow, BOD, pH, Total<br>Suspended Solids, Oil & Grease,<br>Lead, Toluene, Benzene, Ethyl<br>Benzene, Naphthalene, Wet Test  | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Permit is inactive. Remove from list.     |
| GREAT SALT LAKE BASIN WEBER RIVER DRAINAGE                                      |                                    |   |   |   |   |   |
| Silver Creek -> Weber River Snyderville - Silver Creek UT0024414 5/31/97 **     |                                    | Dissolved Oxygen, pH, Total<br>Suspended Solids, Oil & Grease,<br>Flow, Ammonia, Fecal Coliform,<br>Total Coliform, Carbonaceous<br>BOD, Suspended Solids,<br>Cyanide, Arsenic, Beryllium,<br>Cadmium, Copper | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL is approved by EPA. |
| Weber River<br>Town of Oakley<br>8/5/96<br>UT0020061                            | n of Oakley<br>96 **               |   | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL is approved by EPA. |
| Silver Creek WWTP<br>Lucas Western Inc<br>UTP000050<br>6/12/96                  | **                                 |   | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL is approved by EPA. |

<sup>\*-</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

<sup>\*\* -</sup> Stream segment lengths for TMDLs vary for each permit.

Table 1-d. Utah's 1998 303(d) List of Utah Pollution Discharge Elimnation System (UPDES) Permit Renewal Total Maximum Daily Load Analyses (TMDLs) Completed During the 1996-1998 Cycle. Completed TMDLs Will Be Removed When Approved by EPA.

| Waterbody Name (Receiving Water) Permittee Permit Number Date of Permit Renewal      | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)  | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                                  |
|--|------------------------------------|--|---|---|---|---|
| GREAT SALT LAKE BASIN  |                                    |  |   |   |   |   |
| FARMINGTON BAY AREA (GSL)  |                                    |  |   |   |   |   |
| Storm Drain -> Kays Creek -> GSL<br>USAF-Hill Air Force Base<br>UT0023027<br>3/31/98 | **                                 | Flow, pH, Oil & Grease, Wet<br>Test, Lead, Flow, pH, Total<br>Suspended Solids, Oil & Grease,<br>Wet Test, Lead, Flow, pH, Oil<br>& Grease, Wet Test, Lead,<br>Flow, pH, Oil & Grease, Wet<br>Test, Lead, Flow, pH, Total<br>Suspended Solids, Oil & Grease,<br>Wet Test | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL is approved by EPA. |
| Class 6 Ditch -> GSL<br>North Davis Co. Sewer Dist.<br>UT0021741<br>1/31/98          | **                                 | BOD, pH, Total Suspended<br>Solids, Oil & Grease, Ammonia,<br>Chlorine Residual@@  | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL is approved by EPA. |
| GREAT SALT LAKE BASIN  |                                    |  |   |   |   |   |
| Ag. Ditches<br>Tooele City<br>UT0022217<br>1/31/98                                   | **                                 | BOD, pH, Total Suspended<br>Solids, Oil & Grease, Fecal<br>Coliform, Total Coliform@@  |   | No  | 1   | Will remove when TMDL is approved by EPA. |
| GSL<br>Morton International<br>UT0024911<br>4/25/97                                  | **                                 | BOD, pH, Total Suspended<br>Solids, Oil & Grease@@   | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL is approved by EPA. |

<sup>\*-</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

<sup>\*\* -</sup> Stream segment lengths for TMDLs vary for each permit.

Table 1-d. Utah's 1998 303(d) List of Utah Pollution Discharge Elimnation System (UPDES) Permit Renewal Total Maximum Daily Load Analyses (TMDLs) Completed During the 1996-1998 Cycle. Completed TMDLs Will Be Removed When Approved by EPA.

| Waterbody Name (Receiving Water) Permittee Permit Number Date of Permit Renewal | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)  | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                                  |
|---|------------------------------------|--|---|---|---|---|
| GREAT SALT LAKE BASIN   |                                    |  |   |   |   |   |
| BEAR RIVER DRAINAGE   |                                    |  |   |   |   |   |
| Malad River<br>Tremonton City Corp.<br>UT0020303<br>3/31/98                     | **                                 | BOD, pH, Total Suspended<br>Solids, Chlorine Residual,<br>Ammonia, Fecal Coliform, Total<br>Coliform                                 | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL is approved by EPA. |
| GREAT SALT LAKE BASIN   |                                    |  |   |   |   |   |
| JORDAN RIVER DRAINAGE   |                                    |  |   |   |   |   |
| Oil Drain Canal<br>Concrete Products Co.<br>UT0000663<br>6/25/96                | **                                 | Flow, pH, Total Suspended<br>Solids, Oil & Grease,   | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL is approved by EPA. |
| Oil Drain Canal<br>Chevron USA Inc.<br>UT0000175<br>12/31/97                    | **                                 | BOD, pH, Oil & Grease,<br>Ammonia, Chromium, pH,<br>Phenolics, Flow, Chemical<br>Oxygen Demand, Suspended<br>Solids, Wet Test, Lead, | 12/31/98  | Yes   | 1   | Will remove when TMDL is approved by EPA. |
| Storm Drain -> Jordan River<br>Varian Assoc.<br>UT0000701<br>3/31/98            | **                                 | Flow, pH, Total Suspended<br>Solids, Oil & Grease, Copper,<br>Zinc, Oil & Grease, Flow   | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL is approved by EPA. |

<sup>\* -</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

<sup>\*\* -</sup> Stream segment lengths for TMDLs vary for each permit.

Table 1-d. Utah's 1998 303(d) List of Utah Pollution Discharge Elimnation System (UPDES) Permit Renewal Total Maximum Daily Load Analyses (TMDLs) Completed During the 1996-1998 Cycle. Completed TMDLs Will Be Removed When Approved by EPA.

| Waterbody Name (Receiving Water) Permittee Permit Number Date of Permit Renewal | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)   | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                                  |
|---|------------------------------------|---|---|---|---|---|
| Kersey Creek -> C7 Ditch -> GSL<br>Magna Water & Swer<br>UT0021440<br>11/20/96  | **                                 | BOD, pH, Total Suspended<br>Solids, Oil & Grease, Flow,<br>Residual Chlorine, Fecal<br>Coliform, Total Coliform, BOD,<br>Cyanide, Arsenic, Beryllium,<br>Cadmium, Copper, Lead,<br>Thallium, Nickel, Silver, Zinc,<br>Antimony, Selenium, Phenols                         | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL is approved by EPA. |
| Dry Wash<br>Barric Mercur<br>UT0023884<br>12/31/97                              | **                                 | Flow, pH, Total Suspended<br>Solids, Oil & Grease, Cyanide,<br>Sulfate, Cadmium, Copper,<br>Lead, Zinc, Total Dissolved<br>Solids, Mercury, Oil & Grease,<br>Flow, pH, Total Suspended<br>Solids, Oil & Grease, Nitrate,<br>Cyanide, Sulfate, Cadmium                     | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL is approved by EPA. |
| Jordan River<br>South Valley Water Reclam<br>UT0024384<br>7/29/96               | **                                 | Dissolved Oxygen, pH, Total<br>Suspended Solids, Flow, Residual<br>Chlorine Ammonia, Fecal<br>Coliform, Total Coliform,<br>Carbonaceous BOD, Suspended<br>Solids, Wet Test  | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL is approved by EPA. |
| Coon Creek<br>Alliant Techsystems<br>UT0024546<br>8/20/97                       | **                                 | BOD, pH, Total Suspended<br>Solids, Oil & Grease, Kjeldahl<br>Nitrogen,, Phosphorus Benzene,<br>ETHYL Benzene, Toluene,<br>Xylene, Chemical Oxygen<br>Demand, BOD, pH, Total<br>Suspended Solids, Oil & Grease,<br>Kjeldahl Nitrogen, pH, Copper,<br>Lead, Zinc, Aluminum | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL is approved by EPA. |

<sup>\*-</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

<sup>\*\* -</sup> Stream segment lengths for TMDLs vary for each permit.

Table 1-d. Utah's 1998 303(d) List of Utah Pollution Discharge Elimnation System (UPDES) Permit Renewal Total Maximum Daily Load Analyses (TMDLs) Completed During the 1996-1998 Cycle. Completed TMDLs Will Be Removed When Approved by EPA.

| Waterbody Name (Receiving Water) Permittee Permit Number Date of Permit Renewal | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)  | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                                  |
|---|------------------------------------|--|---|---|---|---|
| Storm Drain -> Jordan River<br>Arrow Pacific Plastics<br>UT0025101<br>9/30/97   | **                                 | Flow, pH, Total Suspended<br>Solids, Oil & Grease, Dimethyl<br>Thalate, pH, Oil & Grease   | Completed<br>(96-98<br>Cycle)                     | No  | 1   | Will remove when TMDL is approved by EPA. |
| UPPER COLORADO RIVER GREEN RIVER DRAINAGE                                       |                                    |  |   |   |   |   |
| Willow Creek -> Price River PacifiCorp - Carbon UT0000094                       | **                                 | T otal Dissolved Solids,,<br>Temperature, pH, Total Suspended<br>Solids, Oil & Grease, Iron,<br>Floating Solids, or Visible Foam,<br>Flow, Residual Chlorine, Total<br>Dissolved Solids, Oil & Grease,<br>Wet Test | Completed<br>(96-98 Cycle)                        | No  | 1   | Will remove when TMDL is approved by EPA. |
| Coyote Wash -> White River<br>American Gilsonite Co.<br>UT0000167<br>12/36/97   | **                                 | Flow, pH, Total Suspended Solids,<br>Oil & Grease, Total Dissolved<br>Solids,  | Completed<br>(96-98 Cycle)                        | No  | 1   | Will remove when TMDL is approved by EPA. |
| Green River<br>USBOR-Flaming Gorge<br>UT0020338<br>3/31/98                      | 非非                                 | Flow, BOD, pH, Total Suspended<br>Solids, Residual Chlorine,<br>Ammonia, Fecal Coliform  | Completed (96-98 Cycle)                           | No  | 1   | Will remove when TMDL is approved by EPA. |
| Grimes Wash -> Cottonwood Cr. PacifiCorp-Wilberg UT0022896 10/31/97             | ****                               | Total Dissolved Solids, Flow, pH,<br>Total Suspended Solids, Oil &<br>Grease, Iron, Wet Test,  | Completed (96-98 Cycle)                           | No  | 1   | Will remove when TMDL is approved by EPA. |

<sup>\*-</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

<sup>\*\* -</sup> Stream segment lengths for TMDLs vary for each permit.

Table 1-d. Utah's 1998 303(d) List of Utah Pollution Discharge Elimnation System (UPDES) Permit Renewal Total Maximum Daily Load Analyses (TMDLs) Completed During the 1996-1998 Cycle. Completed TMDLs Will Be Removed When Approved by EPA.

| Waterbody Name (Receiving Water) Permittee Permit Number Date of Permit Renewal | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)   | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                                  |
|---|------------------------------------|---|---|---|---|---|
| Quitchpah Creek - Muddy River<br>Southern Utah<br>UT0022918<br>10/31/97         | **                                 | pH, Total Suspended Solids, Oil<br>& Grease, Iron, Flow, Total<br>Dissolved Solids, pH, Total<br>Suspended Solids, Settleable<br>Solids, Wet Test, Lead   | Completed (96-98 Cycle)                           | No  | 1   | Will remove when TMDL is approved by EPA. |
| Grassy Trail Cr> Price River<br>Sunnyside Coal Company<br>UT0022942<br>7/18/97  | 李安                                 | Total Dissolved Solids, Flow,<br>Dissolved Oxygen, pH, Total<br>Suspended Solids, Oil & Grease,<br>Iron, Floating Solids, Visible<br>Foam, Sanitary Waste, Total<br>Dissolved Solids, Wet Test, Lead,<br>Flow | Completed (96-98 Cycle)                           | No  | 1   | Will remove when TMDL is approved by EPA. |
| Eccle Creek -> Mud Cr> Price River<br>White Oaks Mining<br>UT0022985<br>2/5/97  | र्शन और                            | Total Dissolved Solids, pH, Oil &<br>Grease, Iron, Flow, Total<br>Dissolved Solids  | Completed (96-98 Cycle)                           | No  | 1   | Will remove when TMDL is approved by EPA. |
| Class E Ditch - Ag Ditch<br>Neola Town Water & Sewer<br>UT0023001<br>1/31/98    | 神神                                 | BOD, pH, Total Suspended Solids,<br>Flow, Fecal Coliform, Total<br>Coliform   | Completed (96-98 Cycle)                           | No  | 1   | Will remove when TMDL is approved by EPA. |
| Grimes Wash -> Cottonwood Cr. PacifiCorp-Des Bee Dove UT0023591 7/10/97         | और और                              | Flow, pH, Total Suspended Solids,<br>Settleable Solids, Oil & Grease,<br>Iron, Total Dissolved Solids   | Completed (96-98 Cycle)                           | No  | 1   | Will remove when TMDL is approved by EPA. |
| Deer Cr> Huntington Cr. PacifiCorp-Deer Creek UT0023604 11/30/97                | **                                 | Flow, pH, Total Suspended Solids,<br>Settleable Solids, Oil & Grease,<br>Iron, Total Dissolved Solids   | Completed (96-98 Cycle)                           | No  | 1   | Will remove when TMDL is approved by EPA. |

<sup>\*-</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

<sup>\*\* -</sup> Stream segment lengths for TMDLs vary for each permit.

Table 1-d. Utah's 1998 303(d) List of Utah Pollution Discharge Elimnation System (UPDES) Permit Renewal Total Maximum Daily Load Analyses (TMDLs) Completed During the 1996-1998 Cycle. Completed TMDLs Will Be Removed When Approved by EPA.

| Waterbody Name (Receiving Water) Permittee Permit Number Date of Permit Renewal       | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)   | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                                  |
|---|------------------------------------|---|---|---|---|---|
| <b>Trib. to Price River -&gt; Price River</b> Cyprus Plateau Mining UT0023736 12/9/96 | **                                 | Total Suspended Solids, Floating<br>Solids, Oil & Grease, Iron, Total<br>Dissolved Solids, Flow, pH   | Completed<br>(96-98 Cycle)                        | No  | 1   | Will remove when TMDL is approved by EPA. |
| Coyote Wash -> White River<br>Ziegler Chemical<br>UT0023868<br>1/16/96                | ****                               | Flow, pH, Total Suspended Solids,<br>Oil & Grease, Total Dissolved<br>Solids, Oil & Grease, Flow  | Completed<br>(96-98 Cycle)                        | No  | 1   | Will remove when TMDL is approved by EPA. |
| Green River<br>Intermountain Concrete<br>UT0024015<br>6/10/96                         | 非非                                 | Total Dissolved Solids, Total<br>Suspended Solids, pH, Oil &<br>Grease  | Completed (96-98 Cycle)                           | No  | 1   | Will remove when TMDL is approved by EPA. |
| Icelander Cr> Price River<br>Sunnyside Cogeneration<br>UT0024759<br>7/25/97           | **                                 | Total Dissolved Solids, Wet Test,<br>Lead, Flow, Dissolved Oxygen<br>pH, Total Suspended Solids,<br>Settleable Solids, Oil & Grease,<br>Iron, Floating Solids, OR Visible<br>Foam, Sanitary Waste, Total<br>Dissolved Solids  | Completed (96-98 Cycle)                           | No  | 1   | Will remove when TMDL is approved by EPA. |
| Price River Price Rvr WID (POTW) UT0021814 12/9/96                                    | **                                 | Dissolved Oxygen, BOD, pH, Total Suspended Solids, Oil & Grease, Flow, Residual Chlorine, Total Dissolved Solids, Ammonia, Fecal Coliform, Total Coliform, Cyanide, Arsenic, Beryllium, Cadmium, Copper, Lead, Thallium, Nickel, Silver, Zinc, Antimony, Selenium, Phenols, Mercury | Completed<br>(96-98 Cycle)                        | No  | 1   | Will remove when TMDL is approved by EPA. |
| LOWER COLORADO RIVER BASIN  |                                    | ,   |   |   |   |   |

<sup>\*-</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

<sup>\*\* -</sup> Stream segment lengths for TMDLs vary for each permit.

Table 1-d. Utah's 1998 303(d) List of Utah Pollution Discharge Elimnation System (UPDES) Permit Renewal Total Maximum Daily Load Analyses (TMDLs) Completed During the 1996-1998 Cycle. Completed TMDLs Will Be Removed When Approved by EPA.

| Waterbody Name (Receiving Water) Permittee Permit Number Date of Permit Renewal | Waterbody<br>Size<br>(Miles/Acres) | UPDES Permit Parameters (*)  | Priority for<br>TMDL<br>(High/Low)<br>(Completed) | Targeted<br>for<br>TMDL<br>4/1998 -<br>4/2000 | Number<br>of<br>UPDES<br>Permit<br>Renewals | Comments                                  |  |
|---|------------------------------------|--|---|---|---|---|--|
| VIRGIN RIVER DRAINAGE   |                                    |  |   |   |   |   |  |
| Dry Wash<br>American Azide<br>UT0025062<br>7/10/97                              | **                                 | BOD., pH, Total Suspended<br>Solids, Oill & Grease, Arsenic,<br>Boron, Cadmium, Chromium,<br>Copper, Lead, Zinc, Total<br>Dissolved Solids   | Completed<br>(96-98 Cycle)                        | No  | 1   | Will remove when TMDL is approved by EPA. |  |
| Virgin River<br>St George City Corp<br>UT0024686<br>6/11/96                     | **                                 | Volatile Solids, Total Solids,<br>Arsenic, Selenium, Zinc, Lead,<br>Nickel, Mercury, Chromium,<br>Copper, Cadmium, Dissolved<br>Oxygen, BOD pH, Total<br>Suspended Solids, Oil & Grease,<br>Total Dissolved Solids, Ammonia,<br>Fecal Coliform, Total Coliform,<br>BOD | Completed<br>(96-98 Cycle)                        | No  | 1   | Will remove when TMDL is approved by EPA. |  |
| UPPER COLORADO RIVER BASIN  |                                    |  |   |   |   |   |  |
| Colorado River<br>Moab City<br>UT0020419<br>9/10/97                             | 非非                                 | Total Suspended Solids, BOD,,<br>Cyanide, Wet Test, Oil & Grease,<br>pH  | Completed (96-98 Cycle)                           | No  | 1   | Will remove when TMDL approved by EPA.    |  |

<sup>\*-</sup> Parameters listed with UPDES Permit Renewal TMDLs are effluent limited and may not be a component of the parameter that is causing waterbody impairment. Water quality standards may be violated and water quality impaired if the permitted effluent limits are not met.

<sup>\*\* -</sup> Stream segment lengths for TMDLs vary for each permit.

Table 2-a. Lake and Reservoir Waterbodies to Be Removed from Utah's 1996 303(d) List of Water Quality Impaired Waters.

| Waterbody Name              | Waterbody Size<br>(Acres) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals | Status of<br>TMDL | TMDL<br>Approved<br>by EPA | Reason for Removal  |
|-----------------------------|---------------------------|-------------------------------------|--|-------------------|----------------------------|---|
| GREAT SALT LAKE BASIN       |                           |                                     |  |                   |                            |   |
| UTAH LAKE DRAINAGE          |                           |                                     |  |                   |                            |   |
| Salem Pond                  | 11                        | No                                  |  |                   |                            | New assessment using chemical, physical, and biological data indicated beneficial uses being supported. |
| Butterly Lake               | 5                         | No                                  |  |                   |                            | New assessment using chemical, physical, and biological data indicated beneficial uses being supported. |
| Jordanelle Reservoir        | 10                        | No                                  |  |                   |                            | New assessment using chemical, physical, and biological data indicated beneficial uses being supported. |
| Trial Lake                  | 4                         | No                                  |  |                   |                            | New assessment using chemical, physical, and biological data indicated beneficial uses being supported. |
| GREAT SALT LAKE BASIN       |                           |                                     |  |                   |                            |   |
| WEBER RIVER DRAINAGE        |                           |                                     |  |                   |                            |   |
| Lost Creek Reservoir        | 52                        | No                                  |  |                   |                            | New assessment using chemical, physical, and biological data indicated beneficial uses being supported. |
| Rockport                    | 1,189                     | No                                  |  |                   |                            | New assessment using chemical, physical, and biological data indicated beneficial uses being supported. |
| Willard Bay Reservoir       | 10,000                    | No                                  |  |                   |                            | New assessment using chemical, physical, and biological data indicated beneficial uses being supported. |
| GREAT SALT LAKE BASIN       |                           |                                     |  |                   |                            |   |
| Settlement Canyon Reservoir | 315                       | No                                  |  |                   |                            | New assessment using chemical, physical, and biological data indicated beneficial uses being supported. |

| Waterbody Name          | Waterbody Size<br>(Acres) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals | Status of<br>TMDL | TMDL<br>Approved<br>by EPA | Reason for Removal  |  |
|-------------------------|---------------------------|-------------------------------------|--|-------------------|----------------------------|---|--|
| GREAT SALT LAKE BASIN   |                           |                                     |  |                   |                            |   |  |
| BEAR RIVER DRAINAGE     |                           |                                     |  |                   |                            |   |  |
| Little Creek Reservoir  | 65                        | No                                  |  |                   |                            | New assessment using chemical, physical, and biological data indicated beneficial uses being supported.       |  |
| GREAT SALT LAKE BASIN   |                           |                                     |  |                   |                            |   |  |
| SEVIER RIVER DRAINAGE   |                           |                                     |  |                   |                            |   |  |
| DMAD Reservoir          | 1,199                     | No                                  |  |                   |                            | New assessment using chemical, physical, and biological data indicated beneficial uses being supported.       |  |
| Sevier Bridge Reservoir | 10,905                    | No                                  |  |                   |                            | New assessment using chemical, physical, and biological data indicated beneficial uses being supported.       |  |
| UPPER COLORADO RIVER    |                           |                                     |  |                   |                            |   |  |
| GREEN RIVER DRAINAGE    |                           |                                     |  |                   |                            |   |  |
| Flaming Gorge Reservior | 42,020                    | No                                  |  |                   |                            | Incorrectly placed on list in 1996-1998 cycle. New assessment also indicated beneficial uses being supported. |  |
| Hoop Lake               | 162                       | No                                  |  |                   |                            | New assessment using chemical, physical, and biological data indicated beneficial uses being supported.       |  |
| Joes Valley Reservoir   | 162                       | No                                  |  |                   |                            | New assessment using chemical, physical, and biological data indicated beneficial uses being supported.       |  |
| Oak Park Reservoir      | 382                       | No                                  |  |                   |                            | New assessment using chemical, physical, and biological data indicated beneficial uses being supported.       |  |
| Pine Lake               | 77                        | No                                  |  |                   |                            | New assessment using chemical, physical, and biological data indicated beneficial uses being supported.       |  |
| Redfleet Reservoir      | 520                       | No                                  |  |                   |                            | New assessment using chemical, physical, and biological data indicated beneficial uses being supported.       |  |

| Waterbody Name             | Waterbody Size<br>(Acres) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals | Status of<br>TMDL | TMDL<br>Approved<br>by EPA | Reason for Removal  |
|----------------------------|---------------------------|-------------------------------------|--|-------------------|----------------------------|---|
| UPPER COLORADO RIVER BASIN |                           |                                     |  |                   |                            |   |
| COLORADO RIVER DRAINAGE    |                           |                                     |  |                   |                            |   |
| Donkey Reservoir           | 40                        | No                                  |  |                   |                            | New assessment using chemical, physical, and biological data indicated beneficial uses being supported. |

Table 2-b. River and Stream Waterbodies to Be Removed from Utah's 1996 303(d) Impaired Waters. List of Water Quality

| Waterbody Name   | Waterbody Size<br>(Miles) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals (*) | Status of<br>TMDL | TMDL<br>Approved<br>by EPA | Reason for Removal   |
|--|---------------------------|-------------------------------------|--|-------------------|----------------------------|--|
| GREAT SALT LAKE BASIN  |                           |                                     |  |                   |                            |  |
| UTAH LAKE DRAINAGE   |                           |                                     |  |                   |                            |  |
| Dry Creek<br>Spanish Fork<br>UT0020109                                     | **                        | Yes                                 | 1  | Completed         | Yes                        | TMDL submitted and approved by EPA.  |
| Beer Creek -> Utah Lake<br>Salem City Corp.<br>UT0020249                   | **                        | Yes                                 | 1  | Completed         | Yes                        | TMDL submitted and approved by EPA.  |
| Beer Creek<br>Payson City Corp.<br>UT0020427                               | **                        | Yes                                 | 1  | Completed         | Yes                        | TMDL submitted and approved by EPA.  |
| Jordanelle Res.<br>United Park City Mines<br>UT0022403                     | **                        | Yes                                 | 1  | Completed         | Yes                        | TMDL submitted and approved by EPA.  |
| Millrace Creek,<br>Utah Lake to headwaters                                 | 1.6                       | No                                  |  |                   |                            | Stream segment assessed as fully supporting during this reporting cycle.   |
| Main Creek,<br>Deer Creek Res to Round Valley-tribs                        | 6.0                       | Yes                                 |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Daniels Creek,<br>confluence w/ Deer Creek Reservoir to<br>Whiskey Springs | 10.0                      | Yes                                 |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Snake Creek,<br>confluence w/ Provo River to WMSP Golf<br>Course           | 4.3                       | Yes                                 |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Lake Creek,<br>above Timber Creek confluence to<br>headwaters-tribs        | 18.1                      | Yes                                 |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Spring Creek,<br>confluence w/ Beer Creek to headwaters                    | 11.5                      | No                                  |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |

| Waterbody Name   | Waterbody Size<br>(Miles) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals (*) | Status of<br>TMDL | TMDL<br>Approved<br>by EPA | Reason for Removal   |
|--|---------------------------|-------------------------------------|--|-------------------|----------------------------|--|
| Spanish Fork River,<br>Moark Diversion to Thistle Creek confluence                   | 10.8                      | Yes                                 |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Diamond Fork Creek,<br>Sixth Water Creek confluence to Hawthorne<br>Campground       | 5.0                       | Yes                                 |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Soldier Creek,<br>confluence with Thistle Creek to confluence<br>of Starvation Creek | 17.2                      | Yes                                 |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Sheep Creek, confluence w/ Soldier Creek to headwaters-tribs                         | 6.2                       | Yes                                 |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Clear Creek,<br>confluence w/ Soldier Creek t headwaters-<br>tribs                   | 11.8                      | Yes                                 |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Soldier Creek,<br>confluence of Starvation Creek to headwaters-<br>tribs             | 6.4                       | Yes                                 |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Thistle Creek,<br>confluence w/ Soldier Creek to USFS Forest<br>Boundary             | 18.3                      | Yes                                 |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Thistle Creek,<br>USFS Boundary to headwaters-tribs                                  | 16.8                      | Yes                                 |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Peteetneet Creek,<br>Maple Dell Campground t headwaters-tribs                        | 16.6                      | Yes                                 |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Salt Creek, from mouth of canyon to USFS boudndary.                                  | 6.8                       | Yes                                 |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |

| Waterbody Name  | Waterbody Size<br>(Miles) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals (*) | Status of<br>TMDL | TMDL<br>Approved<br>by EPA | Reason for Removal  |
|---|---------------------------|-------------------------------------|--|-------------------|----------------------------|---|
| GREAT SALT LAKE BASIN   |                           |                                     |  |                   |                            |   |
| WEBER RIVER DRAINAGE  |                           |                                     |  |                   |                            |   |
| Weber River, Ogden River confluence to Cottonwood Ck. confluence            | 23.8                      | Yes                                 |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody |
| East Canyon Creek,<br>confluence w/ Weber R. to East Canyon Dam             | 13.8                      | Yes                                 |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody |
| Huff Creek,<br>confluence w/ Chalk Creek to<br>headwaters-tribs             | 15.5                      | Yes                                 |  | Completed         | Yes                        | TMDL completed and approved by EPA.   |
| Chalk Creek,<br>South Fork confluence to Huff Creek<br>confluence           | 6.5                       | Yes                                 |  | Completed         | Yes                        | TMDL completed and approved by EPA  |
| Chalk Creek,<br>confluence w/ Weber River to South Fork<br>confluence       | 7.4                       | Yes                                 |  | Completed         | Yes                        | TMDL completed and approved by EPA  |
| South Fork Chalk Creek,<br>confluence w/ Chalk Creek to<br>headwaters-tribs | 47.1                      | Yes                                 |  | Completed         | Yes                        | TMDL completed and approved by EPA  |
| Chalk Creek,<br>East Fork Chalk Creek confluence to<br>headwaters-tribs     | 33.4                      | Yes                                 |  | Completed         | Yes                        | TMDL completed and approved by EPA  |
| Chalk Creek,<br>Huff Creek confluence to East Fork<br>confluence            | 9.5                       | Yes                                 |  | Completed         | Yes                        | TMDL completed and approved by EPA  |
| Fort Creek, confluence w/ Weber River to headwaterstribs                    | 10.2                      | Yes                                 |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody |

|   | 1                         |                                     |  |                   |                            |   |
|---|---------------------------|-------------------------------------|--|-------------------|----------------------------|---|
| Waterbody Name  | Waterbody Size<br>(Miles) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals (*) | Status of<br>TMDL | TMDL<br>Approved<br>by EPA | Reason for Removal  |
| GREAT SALT LAKE BASIN   |                           |                                     |  |                   |                            |   |
| Trout Creek, mouth to headwaters  |                           | No                                  |  |                   |                            | Number of samples collected (2) were not sufficient to make a beneficial use assessment. Need more data before assessment is considered acceptable.                         |
| GREAT SALT LAKE BASIN   |                           |                                     |  |                   |                            |   |
| BEAR RIVER DRAINAGE   |                           |                                     |  |                   |                            |   |
| Bear River,<br>Rich County  |                           | No                                  |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody |
| Spring Creek,<br>confluence w/ Little Bear River to<br>headwaters-tribs         | 7.3                       | No                                  |  | Completed         | Yes                        | TMDL was completed and approved by EPA.   |
| Cub River,<br>confluence w/ Bear River to headwaters to<br>Utah-Idaho Stateline | 13.8                      | No                                  |  | Completed         | Yes                        | TMDL was completed and approved by EPA.   |
| Cub River,<br>Utah-Idaho Stateline  | 0.0                       | No                                  |  | Completed         | Yes                        | Waterbody does not exist. Listed to show that Total phosphorus criteria were exceed by waters entering the state from Idaho   |
| Worm Creek,<br>confluence w/ Cub River to headwaters-tribs                      | 2.5                       | No                                  |  | Completed         | Yes                        | TMDL was completed and approved by EPA.   |
| High Creek,<br>confluence w/ Cub River to headwaters-tribs                      | 20.7                      | No                                  |  | Completed         | Yes                        | TMDL was completed and approved by EPA.   |
| Spring Creek(Lewiston),<br>confluence w/ Cub River to Utah-Idaho<br>Stateline   | 3.3                       | No                                  |  | Completed         | Yes                        | TMDL was completed and approved by EPA.   |
| Logan River,<br>Cutler Reservoir to mouth of Logan Canyon                       | 14.4                      | No                                  |  | Completed         | Yes                        | TMDL was completed and approved by EPA.   |
| Bear River,<br>Cutler Reservoir to Idaho Stateline                              | 32.1                      | No                                  |  | Completed         | Yes                        | TMDL was completed and approved by EPA.   |
| Newton Creek,<br>Cutler Reservoir to Newton Reservoir                           | 5.8                       | No                                  |  | Completed         | Yes                        | TMDL was completed and approved by EPA.   |
| GREAT SALT LAKE BASIN   |                           |                                     |  |                   |                            |   |

| Waterbody Name  | Waterbody Size<br>(Miles) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals (*) | Status of<br>TMDL | TMDL<br>Approved<br>by EPA | Reason for Removal  |
|---|---------------------------|-------------------------------------|--|-------------------|----------------------------|---|
| SEVIER RIVER DRAINAGE   |                           |                                     |  |                   |                            |   |
| Otter Creek,<br>Otter Creek Reservoir to Koosharem<br>Reservoir-tribs   |                           | Yes                                 |  | Completed         | Yes                        | TMDL was completed and approved by EPA  |
| Sevier River, Piute Reservoir t headwataers-tribs except Asay Creek, Blue Spring Creek, Clear Creek, Ipson Creek, and Mammouth Creek. |                           | No                                  |  |                   |                            | Waterbody does not exist as described. New waterbody delineated for Sevier River Basin.     |
| Sevier River, Annabelle Diversion to Piute Reservoir  |                           | No                                  |  |                   |                            | Waterbody does not exist as described. New waterbody delineated for Sevier River Basin.     |
| Salina Creek,<br>Sevier River to headwaters (includes Meadow<br>Creek   |                           | No                                  |  |                   |                            | Waterbody does not exist as described. New waterbodies delineated for Sevier River Basin.   |
| Gooseberry Creek,<br>Salina Creek to headwaters   |                           | No                                  |  |                   |                            | Waterbody does not exist as described. New waterbodies delineated for Sevier River Basin.   |
| Salina Creek,<br>confluence of Meadow Creek to headwaters   |                           | No                                  |  |                   |                            | Waterbody does not exist as described. New waterbodies delineated for Sevier River Basin.   |
| San Pitch River,<br>from U-32 crossing to headwaters-tribs  |                           | No                                  |  |                   |                            | Waterbodies does not exist as described. New waterbodies delineated for Sevier River Basin. |
| Sevier River,<br>Sevier Lake to DMAD  |                           | No                                  |  |                   |                            | Waterbody does not exist as described. New waterbodies delineated for Sevier River Basin.   |
| UPPER COLORADO RIVER  |                           |                                     |  |                   |                            |   |
| GREEN RIVER DRAINAGE  Grassy Trail Cr> Price River Sunnyside Coal Company UT0022942   | **                        | Yes                                 | 1  | Completed         | Yes                        | TMDL submitted and approved by EPA.   |
| Price River Price Rvr WID (POTW) UT0021814  | **                        | Yes                                 | 1  | Completed         | Yes                        | TMDL submitted and approved by EPA.   |
| Deer Cr> Huntington Cr. PacifiCorp-Deer Creek UT0023604   | **                        | Yes                                 | 1  | Completed         | Yes                        | TMDL submitted and approved by EPA.   |

|  |                           |                                     |  |                   |                            | -   |
|--|---------------------------|-------------------------------------|--|-------------------|----------------------------|---|
| Waterbody Name   | Waterbody Size<br>(Miles) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals (*) | Status of<br>TMDL | TMDL<br>Approved<br>by EPA | Reason for Removal  |
| Mud Creek,<br>Scofield Reservoir to headwaters                                       |                           | No                                  |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody |
| Winter Quarters Creek, from mouth to headwaters                                      |                           | No                                  |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody |
| Eccles Creek,<br>mouth to headwaters   |                           | No                                  |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody |
| Fish Creek,<br>except Goosesberry from Scofield Reservoir to<br>headwaters           |                           | No                                  |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody |
| Pondtown Creek,<br>Scofield Reservoir to headwaters                                  |                           | No                                  |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody |
| Range Creek,<br>from Green River to Pump House                                       |                           | No                                  |  |                   |                            | New waterbody delineation. Range Creek divided into three waterbodies. One of these was assessed and found fully supporting its beneficial uses.                            |
| Range Creek,<br>from Pump House to headwaters  |                           | No                                  |  |                   |                            | New waterbody delineation. Range Creek divided into three waterbodies. One of these was assessed and found fully supporting its beneficial uses.                            |
| Duchesne River,<br>from confluence of Green River to Myton<br>water treatment intake |                           | No                                  |  |                   |                            | New waterbody definition. This waterbody no longer exists as described.   |
| <b>Duchesne River,</b> from Myton intake to Knight Diversion                         |                           | No                                  |  |                   |                            | New waterbody definition. This waterbody no longer exists as described.   |
| Strawberry River,<br>from confluence with Duchesne River to<br>Starvation Reservoir  |                           | No                                  |  |                   |                            | Stream segment assessed as fully supporting during this reporting cycle. Data collected during Uinta Intensive Monitoring Assessment.                                       |
| Strawberry River,<br>Strawberry Reservoir to headwaters.                             |                           | No                                  |  |                   |                            | New waterbody delineation. Waterbody does not exist as described. All waterbodies in this region were also assessed as fully supporting during this reporting cycle.        |

| Waterbody Name  | Waterbody Size<br>(Miles) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals (*) | Status of<br>TMDL | TMDL<br>Approved<br>by EPA | Reason for Removal   |
|---|---------------------------|-------------------------------------|--|-------------------|----------------------------|--|
| Red Creek,<br>confluence with Strawberry River to Currant<br>Creek  |                           | No                                  |  |                   |                            | Based upon chemical and physical data, stream segment was assessed as fully supporting during this reporting cycle. Data collected during Uinta Intensive Monitoring Assessment. |
| Currant Creek,<br>Red Creek to Currant Creek Reservoir  |                           | No                                  |  |                   |                            | Based upon chemical and physical data, stream segment was assessed as fully supporting during this reporting cycle. Data collected during Uinta Intensive Monitoring Assessment. |
| Duchesne River,<br>Knight diversion to confluence of West Fork<br>Duchesne River                                  |                           | No                                  |  |                   |                            | New waterbody definition. This waterbody no longer exists as described.  |
| West fork of Duchesne River, confluence of<br>Duchesne River to headwaters  |                           | No                                  |  |                   |                            | Based upon chemical and physical data, stream segment was assessed as fully supporting during this reporting cycle. Data collected during Uinta Intensive Monitoring Assessment. |
| <b>Uintah River,</b> Duchesne River to upper diversions   |                           | No                                  |  |                   |                            | New waterbody definition. This waterbody no longer exists as described.  |
| Brush Creek,<br>Green River to confluencr of Big Brush Creek<br>and Little Brush Creek                            |                           | No                                  |  |                   |                            | New waterbody definition. This waterbody no longer exists as described.  |
| LOWER COLORADO RIVER BASIN  |                           |                                     |  |                   |                            |  |
| VIRGIN RIVER DRAINAGE   |                           |                                     |  |                   | _                          |  |
| Virgin River,<br>from Stateline to confluence of North Fork<br>Virgin River With East Fork Virgin River-<br>tribs |                           | No                                  |  |                   |                            | New waterbody definition. This waterbody no longer exists as described.  |
| North Fork Virgin River,<br>from confluence with East Fork to headwaters  |                           | No                                  |  |                   |                            | New waterbody definition. This waterbody no longer exists as described.  |
| Ash Creek, from confluence with Virgin River to headwaters.   |                           | No                                  |  |                   |                            | New waterbody delineation. Ash Creek made into three waterbodies. Waterbody does not exist as described.   |
| Muddy Creek,<br>confluence w/ East Fork Virgin River to<br>headwaters-tribs                                       |                           | No                                  |  |                   |                            | New waterbody definition. This waterbody no longer exists as described.  |
| LOWER COLORADO RIVER BASIN KANAB DRAINAGE   |                           |                                     |  |                   |                            |  |

| Waterbody Name   | Waterbody Size<br>(Miles) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals (*) | Status of<br>TMDL | TMDL<br>Approved<br>by EPA | Reason for Removal   |
|--|---------------------------|-------------------------------------|--|-------------------|----------------------------|--|
| Kanab Creek, from state line to headwaters-tribs       |                           | No                                  |  |                   |                            | New waterbody delineation. Kanab Creek separated into two waterbodies.   |
| SNAKE RIVER BASIN                                      |                           |                                     |  |                   |                            |  |
| Birch Creek,<br>from mouth to Nevada state line        |                           | No                                  |  |                   |                            | Sampling station is at the state line. Waterbody is actually in Idaho. Should not have been listed as being in Utah.   |
| Raft River, from mouth to headwaters at Junction Creek |                           | No                                  |  |                   |                            | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |

Table 3. Status of Waterbodies Targeted for Total Maximum Daily Load Analyses During the 1996-1998 Reporting Cycle.

| Waterbody Name  | Waterbody Size<br>(Miles/Acres) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals | Status of<br>TMDL | TMDL<br>Approve<br>d by<br>EPA | Justification for Rollover/Changes |
|---|---------------------------------|-------------------------------------|--|-------------------|--------------------------------|------------------------------------|
| GREAT SALT LAKE BASIN   |                                 |                                     |  |                   |                                |                                    |
| UTAH LAKE DRAINAGE  |                                 |                                     |  |                   |                                |                                    |
| Ag. Ditch<br>Nephi Rubber<br>UT0025097                              | **                              | Yes                                 | 1  | Completed         | No                             |                                    |
| Ironton Canal -> Utah Lake<br>Reilly Industries Inc.<br>UT0000370   | **                              | Yes                                 | 1  | Completed         | No                             |                                    |
| Ironton Canal -> Utah Lake<br>Pacific States Cast Iron<br>UT0000612 | **                              | Yes                                 | 1  | Completed         | No                             |                                    |
| Dry Creek<br>Spanish Fork<br>UT0020109                              | **                              | Yes                                 | 1  | Completed         | Yes                            |                                    |
| Beer Creek -> Utah Lake<br>Salem City Corp.<br>UT0020249            | **                              | Yes                                 | 1  | Completed         | Yes                            |                                    |
| Beer Creek<br>Payson City Corp.<br>UT0020427                        | **                              | Yes                                 | 1  | Completed         | Yes                            |                                    |
| Spring Creek -> Utah Lake<br>Springville City<br>UT0020834          | **                              | Yes                                 | 1  | Completed         | No                             |                                    |
| Jordanelle Res.<br>United Park City Mines<br>UT0022403              | **                              | Yes                                 | 1  | Completed         | Yes                            |                                    |
| Class 6 Ditch -> Jordan River<br>PacifiCorp - Gadsby<br>UT0000116   | **                              | Yes                                 | 1  | Completed         | No                             |                                    |
| Ditch -> Oil Drain (6) -> GSL<br>Amoco HWMF<br>UT0025071            | **                              | Yes                                 | 1  | Completed         | No                             |                                    |

 $<sup>\</sup>ensuremath{^{**}}$  - Stream segment lengths for TMDLs  $% \ensuremath{^{**}}$  vary for each permit.

| Waterbody Name   | Waterbody Size<br>(Miles/Acres) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals | Status of<br>TMDL               | TMDL<br>Approve<br>d by<br>EPA | Justification for Rollover/Changes  |
|--|---------------------------------|-------------------------------------|--|---------------------------------|--------------------------------|---|
| Main Creek,<br>Deer Creek Res to Round Valley-tribs                                  | 6.0                             | Yes                                 |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing this waterbody. |
| Daniels Creek,<br>confluence w/ Deer Creek Reservoir to<br>Whiskey Springs           | 10.0                            | Yes                                 |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody.    |
| Snake Creek,<br>confluence w/ Provo River to WMSP Golf<br>Course                     | 4.3                             | Yes                                 |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody.    |
| Lake Creek,<br>above Timber Creek confluence to<br>headwaters-tribs                  | 18.1                            | Yes                                 |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody.    |
| Spring Creek,<br>confluence w/ Beer Creek to headwaters                              | 11.5                            | No                                  |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody.    |
| Spanish Fork River,<br>Moark Diversion to Thistle Creek confluence                   | 10.8                            | Yes                                 |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody.    |
| Diamond Fork Creek,<br>confluence w/ Spanish Fork River to Sixth<br>Water confluence | 19.4                            | Yes                                 |  | Rollover                        |                                | Additional staff needed to complete TMDL. Will be scheduled as part of 12 year cycle.   |
| Diamond Fork Creek,<br>Sixth Water Creek confluence to Hawthorne<br>Campground.      | 5.0                             | Yes                                 |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody.    |
| Sixth Water Creek,<br>confluence w/ Diamond Fork Creek to<br>headwaters-tribs        | 12.4                            | Yes                                 |  | Rollover                        |                                | Additional staff needed to complete TMDL. Will be scheduled as part of 12 year cycle.   |

 $<sup>\</sup>ensuremath{^{**}}$  - Stream segment lengths for TMDLs  $% \ensuremath{^{**}}$  vary for each permit.

| Waterbody Name   | Waterbody Size<br>(Miles/Acres) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals | Status of<br>TMDL               | TMDL<br>Approve<br>d by<br>EPA | Justification for Rollover/Changes   |
|--|---------------------------------|-------------------------------------|--|---------------------------------|--------------------------------|--|
| Soldier Creek,<br>confluence with Thistle Creek to confluence<br>of Starvation Creek | 17.2                            | Yes                                 |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Sheep Creek,<br>confluence w/ Soldier Creek to<br>headwaters-tribs                   | 6.2                             | Yes                                 |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Clear Creek,<br>confluence w/ Soldier Creek to<br>headwaters-tribs                   | 11.8                            | Yes                                 |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Soldier Creek,<br>confluence of Starvation Creek to<br>headwaters-tribs              | 6.4                             | Yes                                 |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Thistle Creek,<br>confluence w\ Soldier Creek to USFS Forest<br>Boundary             | 18.3                            | Yes                                 |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Thistle Creek,<br>USFS Boundary to headwaters-tribs                                  | 16.8                            | Yes                                 |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Peteetneet Creek,<br>Maple Dell Campground to headwaters-tribs                       | 16.6                            | No                                  |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Salt Creek,<br>from mouth of Canyon to USFS Boundary                                 | 6.8                             | No                                  |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |

 $<sup>\</sup>ensuremath{^{**}}$  - Stream segment lengths for TMDLs  $% \ensuremath{^{**}}$  vary for each permit.

| Waterbody Name   | Waterbody Size<br>(Miles/Acres) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals | Status of<br>TMDL               | TMDL<br>Approve<br>d by<br>EPA | Justification for Rollover/Changes   |
|--|---------------------------------|-------------------------------------|--|---------------------------------|--------------------------------|--|
| GREAT SALT LAKE BASIN  |                                 |                                     |  |                                 |                                |  |
| WEBER RIVER DRAINAGE   |                                 |                                     |  |                                 |                                |  |
| Silver Creek -> Weber River<br>Snyderville - Silver Creek<br>UT0024414 | **                              | Yes                                 | 1  | Completed                       |                                |  |
| Weber River<br>Town of Oakley<br>UT0020061                             | **                              | Yes                                 | 1  | Completed                       |                                |  |
| Silver Creek WWTP<br>Lucas Western Inc<br>UTP000050                    | **                              | Yes                                 | 1  | Completed                       |                                |  |
| Weber River,<br>Ogden River confluence to Cottonwood Ck.<br>confluence | 23.8                            | Yes                                 |  | Removed from 303(d) list.       |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| East Canyon Creek,<br>confluence w/ Weber R. to East Canyon<br>Dam     | 13.8                            | Yes                                 |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| East Canyon Creek,<br>East Canyon Reservoir to headwaters              | 30.7                            | Yes                                 |  | Rollover                        |                                | More staff needed. Will become part of 12 year schedule.   |
| Weber River,<br>nyon Creek confluence to Lost Creek<br>confluence      | 14.7                            | Yes                                 |  | Removed<br>from 303(d)<br>list. | _                              | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Francis Creek,<br>Lost Creek Res. to headwater-tribs                   | 4.4                             | Yes                                 |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |

 $<sup>\</sup>ensuremath{^{**}}$  - Stream segment lengths for TMDLs  $% \ensuremath{^{**}}$  vary for each permit.

| Waterbody Name  | Waterbody Size<br>(Miles/Acres) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals | Status of<br>TMDL               | TMDL<br>Approve<br>d by<br>EPA | Justification for Rollover/Changes   |
|---|---------------------------------|-------------------------------------|--|---------------------------------|--------------------------------|--|
| Lost Creek,<br>Lost Creek Res. to headwaters-tribs                          | 67.5                            | Yes                                 |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Echo Creek, confluence w/ Weber R. to headwaters-tribs                      | 43.0                            | Yes                                 |  | Rollover                        |                                | Additional staff needed to complete TMDL. Will be scheduled as part of 12 year cycle.  |
| Huff Creek,<br>confluence w/ Chalk Creek to<br>headwaters-tribs             | 15.5                            | Yes                                 |  | Completed                       | Yes                            |  |
| Chalk Creek,<br>South Fork confluence to Huff Creek<br>confluence           | 6.5                             | Yes                                 |  | Completed                       | Yes                            |  |
| Chalk Creek,<br>confluence w/ Weber River to South Fork<br>confluence       | 7.4                             | Yes                                 |  | Completed                       | Yes                            |  |
| South Fork Chalk Creek,<br>confluence w/ Chalk Creek to<br>headwaters-tribs | 47.1                            | Yes                                 |  | Completed                       | Yes                            |  |
| Chalk Creek, East Fork Chalk Creek confluence to headwaters-tribs           | 33.4                            | Yes                                 |  | Completed                       | Yes                            |  |
| Weber River,<br>Echo Res. to Rockport Res.                                  | 10.7                            | Yes                                 |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| Silver Creek,<br>confluence w/ Weber River to<br>headwaters-tribs           | 21.4                            | Yes                                 |  | Rollover                        |                                | More staff needed to complete TMDL. Will become part of 12 year TMDL schedule.   |

 $<sup>\</sup>ensuremath{^{**}}$  - Stream segment lengths for TMDLs  $% \ensuremath{^{**}}$  vary for each permit.

| Waterbody Name  | Waterbody Size<br>(Miles/Acres) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals | Status of<br>TMDL               | TMDL<br>Approve<br>d by<br>EPA | Justification for Rollover/Changes   |
|---|---------------------------------|-------------------------------------|--|---------------------------------|--------------------------------|--|
| Fort Creek,<br>confluence w/ Weber River to<br>headwaters-tribs           | 10.2                            | Yes                                 |  | Removed<br>from 303(d)<br>list. |                                | Change in method of assessing impairment. Total phosphorus data not used by itself to determine beneficial use support. Additional data required before listing a waterbody. |
| East Canyon Reservoir   | 173                             | Yes                                 |  | Rollover                        |                                | TMDL is being worked on. Will become part of 12 TMDL schedule.   |
| GREAT SALT LAKE BASIN   |                                 |                                     |  |                                 |                                |  |
| FARMINGTON BAY AREA (GSL)   |                                 |                                     |  |                                 |                                |  |
| Storm Drain -> Kays Creek -> GSL<br>USAF-Hill Air Force Base<br>UT0023027 | **                              | Yes                                 | 1  | Completed                       | No                             |  |
| Class 6 Ditch -> GSL<br>North Davis Co. Sewer Dist.<br>UT0021741          | **                              | Yes                                 | 1  | Completed                       | No                             |  |
| Stone Creek Air Products & Chemical, Inc. UT002410                        | **                              | Yes                                 | 1  | Scheduled<br>1998-2000          | No                             | Was not due until 9/30/98, placed on 1998 list   |
| GREAT SALT LAKE BASIN   |                                 |                                     |  |                                 |                                |  |
| Ag. Ditches<br>Tooele City<br>UT0022217                                   | **                              | Yes                                 | 1  | Completed                       | No                             |  |
| GSL<br>Morton International<br>UT0024911                                  | **                              | Yes                                 | 1  | Completed                       | No                             |  |
| GREAT SALT LAKE BASIN   |                                 |                                     |  |                                 |                                |  |
| BEAR RIVER DRAINAGE   |                                 |                                     |  |                                 |                                |  |
| Malad River<br>Tremonton City Corp.<br>UT0020303                          | 林林                              | Yes                                 | 1  | Completed                       | No                             |  |

 $<sup>\</sup>ensuremath{^{**}}$  - Stream segment lengths for TMDLs  $% \ensuremath{^{**}}$  vary for each permit.

| Waterbody Name  | Waterbody Size<br>(Miles/Acres) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals | Status of<br>TMDL | TMDL<br>Approve<br>d by<br>EPA | Justification for Rollover/Changes   |
|---|---------------------------------|-------------------------------------|--|-------------------|--------------------------------|--|
| GREAT SALT LAKE BASIN   |                                 |                                     |  |                   |                                |  |
| SEVIER RIVER DRAINAGE   |                                 |                                     |  |                   |                                |  |
| Otter Creek,<br>Otter Creek Reservoir to Koosharem<br>Reservoir-tribs |                                 | Yes                                 |  | Completed         | Yes                            | Non Point Source Project.  |
| Beaver River,<br>Minersville to headwaters-tribs                      |                                 | Yes                                 |  | Rollover          |                                | Non Point Source Project - More data are being collected. Will scheduled during 12 year TMDL schedule. |
| GREAT SALT LAKE BASIN   |                                 |                                     |  |                   |                                |  |
| JORDAN RIVER DRAINAGE   |                                 |                                     |  |                   |                                |  |
| Oil Drain Canal<br>Concrete Products Co.<br>UT0000663                 | **                              | Yes                                 | 1  | Completed         | No                             |  |
| Oil Drain Canal<br>Chevron USA Inc.<br>UT0000175                      | **                              | Yes                                 | 1  | Completed         | No                             |  |
| Storm Drain -> Jordan River<br>Varian Assoc.<br>UT0000701             | **                              | Yes                                 | 1  | Completed         | No                             |  |
| Kersey Creek -> C7 Ditch -> GSL<br>Magna Water & Swer<br>UT0021440    | **                              | Yes                                 | 1  | Completed         | No                             |  |
| Dry Wash<br>Barric Mercur<br>UT0023884                                | **                              | Yes                                 | 1  | Completed         | No                             |  |
| Jordan River<br>South Valley Water Reclam<br>UT0024384                | **                              | Yes                                 | 1  | Completed         | No                             |  |
| Coon Creek<br>Alliant Techsystems<br>UT0024546                        | **                              | Yes                                 | 1  | Completed         | No                             |  |

 $<sup>\</sup>ensuremath{^{**}}$  - Stream segment lengths for TMDLs  $% \ensuremath{^{**}}$  vary for each permit.

| Waterbody Name   | Waterbody Size<br>(Miles/Acres) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals | Status of<br>TMDL               | TMDL<br>Approve<br>d by<br>EPA | Justification for Rollover/Changes  |
|--|---------------------------------|-------------------------------------|--|---------------------------------|--------------------------------|---|
| Storm Drain -> Jordan River<br>Arrow Pacific Plastics<br>UT0025101             | N: N:                           | Yes                                 | 1  | Completed                       | No                             |   |
| Mill Creek,<br>I-15 to Forest Service Boundary                                 | 8.9                             | Yes                                 |  | Rollover                        |                                | Additional staff needed to complete. Will become part of 12-year TMDL schedule.                 |
| Mill Creek,<br>USFS Boundary to headwaters-tribs                               | 14.4                            | Yes                                 |  | Rollover                        |                                | Additional staff needed to complete. Will become part of 12-year TMDL schedule.                 |
| <b>Big Cottonwood Creek</b> ,<br>Jordan River to Forest Service Boundary       | 9.8                             | Yes                                 |  | Rollover                        |                                | Additional staff needed to complete. Will become part of 12-year TMDL schedule.                 |
| Little Cottonwood Creek, confluence<br>Jordan River to Forest Service Boundary | 10.9                            | Yes                                 |  | Rollover                        |                                | Additional staff needed to complete. Will become part of 12-year TMDL schedule.                 |
| Little Cottonwood Creek, Metropolitan WTP to headwaters-tribs                  | 24.5                            | Yes                                 |  | Rollover                        |                                | Additional staff needed to complete. Will become part of 12-year TMDL schedule.                 |
| Jordan River,<br>6400 S to 7800 S  | 2.0                             | Yes                                 |  | Rollover                        |                                | Additional staff needed to complete. Will become part of 12-year TMDL schedule.                 |
| Jordan River,<br>7800 S to Bluffdale   | 14.3                            | Yes                                 |  | Rollover                        |                                | Additional staff needed to complete. Will become part of 12-year TMDL schedule.                 |
| Bingham Creek,<br>confluence w/ Jordan River to<br>headwaters-tribs            | 12.9                            | Yes                                 |  | Rollover                        |                                | Additional staff needed to complete. Will become part of 12-year TMDL schedule.                 |
| Jordan River,<br>Bluffdale to Narrows  | 4.2                             | Yes                                 |  | Rollover                        |                                | Additional staff needed to complete. Will become part of 12-year TMDL schedule.                 |
| Jordan River,<br>Narrows to Utah Lake  | 12.0                            | Yes                                 |  | Rollover                        |                                | Additional staff needed to complete. Will become part of 12-year TMDL schedule.                 |
| Barney Creek from mouth to headwaters  |                                 | No                                  |  | Removed<br>from 303(d)<br>list. |                                | Barney Creek listed on an evaluated basis, data need to be collected before listing.            |
| Midas Creek from mouth to headwaters   |                                 | No                                  |  | Removed<br>from 303(d)<br>list. |                                | Midas Creek listed on an evaluated basis, not assessed. No data to confirm it should be listed. |
| Rose Creek from mouth to headwaters  |                                 | No                                  |  | Removed<br>from 303(d)<br>list. |                                | Rose Creek listed on an evaluated basis, not assessed. No data to confirm it should be listed.  |

 $<sup>\</sup>ensuremath{^{**}}$  - Stream segment lengths for TMDLs  $% \ensuremath{^{**}}$  vary for each permit.

| Waterbody Name   | Waterbody Size<br>(Miles/Acres) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals | Status of<br>TMDL | TMDL<br>Approve<br>d by<br>EPA | Justification for Rollover/Changes                                  |
|--|---------------------------------|-------------------------------------|--|-------------------|--------------------------------|---|
| Parley's Creek from 13th East to Little Dell<br>Reservoir            |                                 | Yes                                 |  | Rollover          |                                | Additional staff needed. Will become part of 12-year TMDL schedule. |
| UPPER COLORADO RIVER   |                                 |                                     |  |                   |                                |   |
| GREEN RIVER DRAINAGE   |                                 |                                     |  |                   |                                |   |
| Willow Creek -> Price River PacifiCorp - Carbon UT0000094            | **                              | Yes                                 | 1  | Completed         | No                             |   |
| Coyote Wash -> White River<br>American Gilsonite Co.<br>UT0000167    | **                              | Yes                                 | 1  | Completed         | No                             |   |
| Green River<br>USBOR-Flaming Gorge<br>UT0020338                      | **                              | Yes                                 | 1  | Completed         | No                             |   |
| Grimes Wash -> Cottonwood Cr. PacifiCorp-Wilberg UT0022896           | **                              | Yes                                 | 1  | Completed         | No                             |   |
| Quitchpah Creek - Muddy River<br>Southern Utah<br>UT0022918          | 非非                              | Yes                                 | 1  | Completed         | No                             |   |
| Grassy Trail Cr> Price River<br>Sunnyside Coal Company<br>UT0022942  | **                              | Yes                                 | 1  | Completed         | Yes                            |   |
| Eccle Creek -> Mud Cr> Price River<br>White Oaks Mining<br>UT0022985 | **                              | Yes                                 | 1  | Completed         | No                             |   |
| Class E Ditch - Ag Ditch<br>Neola Town Water & Sewer<br>UT0023001    | **                              | Yes                                 | 1  | Completed         | No                             |   |

 $<sup>\</sup>ensuremath{^{**}}$  - Stream segment lengths for TMDLs  $% \ensuremath{^{**}}$  vary for each permit.

| Waterbody Name  | Waterbody Size<br>(Miles/Acres) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals | Status of<br>TMDL | TMDL<br>Approve<br>d by<br>EPA | Justification for Rollover/Changes |
|---|---------------------------------|-------------------------------------|--|-------------------|--------------------------------|------------------------------------|
| Grimes Wash -> Cottonwood Cr. PacifiCorp-Des Bee Dove UT0023591           | **                              | Yes                                 | 1  | Completed         | No                             |                                    |
| Deer Cr> Huntington Cr. PacifiCorp-Deer Creek UT0023604                   | **                              | Yes                                 | 1  | Completed         | No                             |                                    |
| Trib. to Price River -> Price River<br>Cyprus Plateau Mining<br>UT0023736 | **                              | Yes                                 | 1  | Completed         | No                             |                                    |
| Coyote Wash -> White River<br>Ziegler Chemical<br>UT0023868               | **                              | Yes                                 | 1  | Completed         | No                             |                                    |
| Green River<br>Intermountain Concrete<br>UT0024015                        | **                              | Yes                                 | 1  | Completed         | No                             |                                    |
| Icelander Cr> Price River<br>Sunnyside Cogeneration<br>UT0024759          | **                              | Yes                                 | 1  | Completed         | No                             |                                    |
| Price River<br>Price Rvr WID (POTW)<br>UT0021814                          | **                              | Yes                                 | 1  | Completed         | No                             |                                    |

 $<sup>\</sup>ensuremath{^{**}}$  - Stream segment lengths for TMDLs  $% \ensuremath{^{**}}$  vary for each permit.

| Waterbody Name                                   | Waterbody Size<br>(Miles/Acres) | Targeted<br>for TMDL<br>4/96 - 4/98 | Number of<br>UPDES<br>Permit<br>Renewals | Status of<br>TMDL | TMDL<br>Approve<br>d by<br>EPA | Justification for Rollover/Changes |
|--|---------------------------------|-------------------------------------|--|-------------------|--------------------------------|------------------------------------|
| LOWER COLORADO RIVER BASIN                       |                                 |                                     |  |                   |                                |                                    |
| VIRGIN RIVER DRAINAGE                            |                                 |                                     |  |                   |                                |                                    |
| Dry Wash<br>American Azide<br>UT0025062          | 非常                              | Yes                                 | 1  | Completed         | No                             |                                    |
| Virgin River<br>St George City Corp<br>UT0024686 | **                              | Yes                                 | 1  | Competed          | No                             |                                    |
| UPPER COLORADO RIVER BASIN                       |                                 |                                     |  |                   |                                |                                    |
| COLORADO RIVER DRAINAGE                          |                                 |                                     |  |                   |                                |                                    |
| Colorado River<br>Moab City<br>UT0020419         | 非非                              | Yes                                 | 1  | Completed         | No                             |                                    |

98em303.wpd

 $<sup>\</sup>ensuremath{^{**}}$  - Stream segment lengths for TMDLs  $% \ensuremath{^{**}}$  vary for each permit.